

JAN 24 1996

KENT COUNTY REMONUMENTATION

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
KENT COUNTY
(County)

Located In:

Corner Code #

1. Public Land Survey

T _____ R _____

T _____ R _____

T R

T R

2. Property Controlling in Section

S 21 T 6N R 11W

S. T. R.

3. Miscellaneous

S. T. R.

Property in Section

S _____ T _____ R _____

Wit. Mon. on
N-S 1/4 line
Sec. 21

4. Lot No. _____, Recorded Plat _____

5. Private Claims

I, Kirk Breitels, in a field survey on March 30, 19 95

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1837	GLO	Not set
------	-----	---------

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Established the intersection of the N-S 1/4 line of Sec. 21, T6N, R11W and the North line of "Churchill Downs No. 4" (Liber 93 of Plats, Page 2).

SEE LCRC # 8816 for information on C 1/4 corner, Sec. 21, T6N, R11W.

P.A. 345 1990 KENT COUNTY

PEER APPROVED

CHAIRMAN

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Standard Kent Co. Witness Monument at location per above

Capped Rerod (Lot Corner) S70°W 10.95'

Set Nail & KC Remon. tag SE side 15" Poplar N25°E 57.72'

SE corner house (siding) N40°E 168.73'

Rerod (Lot Corner) N70°E 25.01'

NW corner chimney foundation S60°E 107.83'

Computed C 1/4 corner Sec. 21 South 240.56'



Signed by _____

Date _____

Surveyor's Michigan License No. 30077

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN. 1981