

SURVEY & REMONUMENTATION

Kent County Remonumentation

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD

SEP 03 1999

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

94 NOV 29 AM 9:22

For corners in
Kent

SECTION

Located In:

Corner Code #

1. Public Land Survey T 6N R 12W H-3
T R Witness
T R Monument
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

I, Randy Kolehouse, in a field survey on May 9, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-3	1831	G.L.O. Notes	L. Lyon	Set Post
	NA	Wit. Map	K.C. Surveyor	R.R. Iron
	1990	L.C.R.C. #5327	Bueche	Set Ref. Mon. 116.23/East of Corner

The position of this corner was previously approved by the Kent County Remonumentation Peer Group monumented by John C. Bueche on 3/20/90 and was recorded per L.C.R.C. #5327.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-3 Found K.C. Monument 116.23 East of H-3 as set by John C. Bueche as a reference corner per L.C.R.C. #5327.

L.C.R.C. #5327

Remon. tag & nail C/L R.R. in tie East 35.50'
Remon. tag & nail W side 8" Poplar N 70° W 7.10'
Remon. tag & nail N side 18" dbl. Poplar S 70° E 3.40'
Remon. tag & nail R.R. tie for switch (N tie, W end) N 65° E 19.63'
East edge of pond West 21' ±

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-3 Standard Kent County Monument (Reference Monument)

Nail & K.C. remon. tag C/L R.R. in tie East 35.50'
Nail & K.C. remon. tag W side 8" Poplar N 70° W 7.10'
Nail & K.C. remon. tag N side 18" dbl. Poplar S 70° E 3.40'
Nail & K.C. remon. tag R.R. tie for switch (N tie, W end) N 65° E 19.63'
East edge of pond West 21' ±
S 1/4 Cor. Section 3 West 116.23' (No Corner Set)

P.A. 345 1990 KENT COUNTY
PEER APPROVED
CHAIRMAN



Signed by Randy J. Kolehouse
Surveyor's Michigan License No. 25854

Date 11/21/94