STATE OF LUMBER RECEIVED FOR EFFICIENCE

Kent County Remonumentation LAND CORNER RECORDATION CERTIFICATE

Fo	corners in	Filing Require	ement of Act 74, Mich. P.A. 1970	o as after 53 Villo: 3	Ú	
		•	SURVEY &	1 3 8		
_	Kent (County)	Located In:	ComPENSHUMENTA"	TION Control		
1.	Public Land Survey	. T R T R T R	Other Code 1996	REG. OF THEOS	٠	
2	Property Controlling	s 22 T10N R 9W	COMM SSION			
۷.	in Section	s 27 T10N R 9W		`6795	•	
3.	Miscellaneous	S T R	D.	naistau of Danda Stamp & File	. Bl	
	Property in Sec.	S R	The state of the s	egister of Deeds Stamp & File		
		ecorded Plat		- ABCDEFGH	I J K L M	
J.				2 6 5 4 3 3 3	2	
				4 7 8 9 10-	11 12	
I, John C. Bueche, in a field survey on June 19 93 , 5					4-4-1	
	do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a					
			of Land Surveyors or by a Decree of a monumented, recovered, found as	9	<u>. </u>	
	ressed below:	o colubilitios, monamentos, vo		10 30 29 28 27-	26 25	
NC	TE: Not more than 4 co	orners, all in the same town a	nd range, may be recorded	11	1-1-1-1	
	on this certificate.			12 31 32 33 34	35 36	
			d/or subasquant restantion:	13		
A. Description of original monument and accessories and/or subsequent restoration:						
	This point never	set by G.L.O.	•			
		•				
	•					
				•		
	•					
В.	B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:					
	Cob witness	et witness monument 516.60' E. of the N 1/4 Cor Sec. 27 on the line of Sec. 27.				
	set withess mondi	ent 510.60. E. OI the	e N 1/4 Cor Sec. 2/ on the	e line of Sec. 27.		
			;			
			•			
•		•		•	-	
					•	

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Std. K.C. Mon. (Harrison 4" x 30") 516.60' E of the N 1/4

cor. Sec. 27 on the N Line of Sec. 27

Nail & K.C. Remon. Tag E side of 18" Willow South 28.13'

NW cor. frame hse. S 50° W 180.80'

NE cor. conc. step (1st step) hse. #12489 18 Mile Rd. 137.10'

East line of hse, #12489 18 Mile Rd. is West 24'±

Section of the corner:

**Authorized to perpetuate locating the position of the corner:

Set Std. K.C. Mon. (Harrison 4" x 30") 516.60' E of the N 1/4

cor. Sec. 27

Nail & K.C. Remon. Tag E side of 18" Willow South 28.13'

NW cor. frame hse. S 50° W 180.80'

NE cor. conc. step (1st step) hse. #12489 18 Mile Rd. is West 24'±

**Authorized to the corner:

**Authorized t A TO LAND 130 IARD S edge Lake N 4'+ Meas, by hand

Signed by Surveyor's Michigan License No. 13027

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1911 REVISED MAY 14, 1975 REVISED JAN.. 1983

OF MICHIGA

JOHN C BUECHE LAND SURVEYOR