

SURVEY & REMONUMENTATION

MAY 22 2000

KENT COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

KENT COUNTY

(County)

Located in:

Corner Code #

Tyrone Twp.

1. Public Land Survey

T10N R. 12W

A-6

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Kirk Breitels, in a field survey on Sept. 20, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-6 1837	GLO	Brookfield	Set Post
1981	LCRC #2068	Nederveld	Set Capped Iron on Sec. Line at midpoint between Sec. Corners
1983	LCRC #3241	Byl	Set Kent County Monument
1994	LCRC #7517	J. Glaza	Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by William R. Byl on 3-21-83 and was recorded per LCRC #3241.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-6 Found Kent County Monument (Harrison) per witnesses from above LCRC as set by William R. Byl in place of the Capped Rod he found. Said Capped Rod checks with LCRC #2068.

LCRC #3241

Nail & Remon. tag P. Pole N20°W 170.15'

LCRC #7517

Nail & Remon. tag P. Pole N15°E 170.15'

Nail & Remon. tag Serv. Pole S30°W 244.29'

Cut "X" S. end conc. culvert N21°W 110.48'

On C/L North-South road

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-6 Standard Kent County Monument

Nail & KC Remon. tag W. side P. Pole N15°E 170.14'

Nail & KC Remon. tag W. side Serv. Pole S30°E 244.29'

"X" on top South end concrete culvert N21°W 110.51'

Capped Rod (N & J) East 49.94'

Nail & KC Remon. tag top wood fence post S50°W 73.20'

On C/L North-South asphalt road.

P.A. 345 1990 KENT COUNTY

PEER APPROVED

CHAIRMAN

Date

30077

Signed by

Surveyor's Michigan License No.

REG. OF DEEDS

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD
1999 NOV - 1 AM 8:37

11485

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

