

.AY % % 2008

KENT COUNTY REMONUMENTATION

|--|

LAND CORNER RECORDATION CERTIFIED Filling Requirement of Act 74, Mich. P.A.	. 1970	390 HA	RECEIPT
Corner Code #  Tyrone Twp.  10NR 12W I-5  R	REC. OF CITEDS	W 24 W 83	ALL SOLUTION WEST
		S	ža *


For corners in KENT COUNTY Located In: 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

11173Register of Deeds Stamp & File Number

4. Lot No, 5. Private Claims _	Recorded Plat		
Kirk Breitels	, in a field survey on	Jan. 22 19 99	do hereby state that unde

conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



P.A. 345 1990 KENT COUNTY

PEER APPROVED Z/25/8 CHAIRMAN fam of tub

## A. Description of original monument and accessories and/or subsequent restoration:

I-5	1837	GLO	Whitcomb	Set Post
	1930-6	7 Kent Co. Wits		Iron - ½" Iron in Mon. Box
	1975	LCRC #824	Bonnema	½" Iron in Mon. Box
	1983	LCRC #3433	Bueche	Set Kent County Monument in Mon. Box
	1991	LCRC #6006	Byl	Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by John C. Bueche on 5-24-83 and was recorded per LCRC #3433.

## Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Kent County Monument (Harrison) per witnesses from above LCRC as set by John C. Bueche in place of the Iron he found inside a Mon. Box. Said Iron checks with Kent Co. Wit. and LCRC #824.

LCRC #3433		LCRC #6006	
PK Nail P. Pole	N45°E 57.77'	Nail & Remon. tag P. Pole	N45°E 57.72'
PK Nail Tel. Pole	N25°W 60.68'	Nail & Remon. tag Tel. Pole	N25°W 60.68'
PK Nail Tel. Pole	S25°W 92.00	Nail & Remon. tag Tel. Pole	S25°W 92.03'
"X" cut in conc. curb	S75°W 43.46'	"X" cut in conc. curb	°S75°W 43.48'
"X" cut in conc. curb	S25°E 40.44'	"X" cut in conc. curb	S25°E 40.44'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

evidence of the position of the original corner.

evidence of the position of the original corner.

•.	Description of monument for contenant accessorie	a caraniiai i	su to per	۲
	I-5 Standard Kent County Monument in Mon. B	ox		
	Nail & KC Remon. tag NW side P. Pole	N45°E	57.72	
	Nail & KC Remon. tag W. side 8" Pine	N30°W	72.36	
	Nail & KC Remon. tag W. side Tel. Pole	S25°W	92.03	
	"X" cut on concrete curb	S75°W	43.52	
	"X" cut on concrete curb	S25°E	40,47°	
	C/L blacktop road E-W is South 1' ±			
	On C/L gravel road N-S +			

OF MICHIGA K!RK BREITELS LAND SURVEYOR NO COLAND

Signed by

Surveyor's Michigan License No.