

SECTION

## KENT COUNTY REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requirement of Act 74, Mich. P.A. 19		
KENT COUNTY	Located In:	Corner Code #	į
(County)	1 ONT -	Tyrone Twp.	
Public Land Survey		R12W	į
2. Property Controlling	s †;	?	


11179 Register of Deeds Stamp & File Number

in Section 3. Miscellaneous Property in Sec.

4. Lot No. \_, Recorded Plat \_ 5. Private Claims

Kirk Breitels 19.99 Jan. 19 in a field survey on do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



Description of original monument and accessories and/or subsequent restoration:

I-12 1837 1971 1982 1991	GLO Kent Co. Wits LCRC #89 LCRC #3010 LCRC #6013	Whitcomb Chambers Starr Byl	Set Post Iron over Stone Iron Set Kent County Monument in Mon. Box Kent County Monument in Mon. Box
-----------------------------------	--	-----------------------------	---

P.A. 345 1989 KENT COUNTY PEER APPROVED 2/25/ CHAIRMA

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Thomas C. Starr on 8-2-82 and was recorded per LCRC #3010.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-12 Found Kent County Monument (Harrison) per witnesses from above LCRC as set by Thomas C. Starr in place of the 3/4" Iron Pipe over a 3/4 Iron Pipe he found in a Mon. Box. Both Iron Pipes check with Kent Co. Wit. and LCRC #89. LCRC #3010 LCRC #6013

Nail & Remon. tag 20" Tree S85°E 59.28" Nail & Remon. tag 24" Ash S85°E 59.26' Nail & Remon. tag P. Pole N25°W 69.72' Nail & Remon. tag P. Pole N25°W 69.72' Nail & Remon. tag P. Pole S45°W 51.45' Nail & Remon. tag P. Pole S45°W 51 43' C/L top Bell Ungrd. Box S50°E 43.80' C/L top of Bell Ungrd. Box S50°E 43.60' SW cor. back of curb at end S75°W 49.00' SW cor. back of curb at end S75°W 48.95' NW cor. back of curb at end N70°W 49.33' NW cor. back of curb at end N70°W 49.30'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-12 Standard Kent County Monument in Mon. Box Nail & KC Remon. tag NE side P. Pole N25°W 69.72' Nail & KC Remon, tag NW side P. Pole S45°W 51.43' C/L top of Tele. Underground Box S50°E 43.70' SW cor. of back of curb at W. end curb and gutter S75°W 48.95' NW cor. of back of curb at W. end curb and gutter N70°W 49.30' Nail & KC Remon. tag N. side 12" Pine N70°E 76.35' On C/L road N-S & W+

OF MICH KIRK **BREITELS** LAND **SURVEYOR** NO 30077 SEDLAND

Signed by 30077 Surveyor's Michigan License No.