

SURVEY & REMONUMENTATION

JAN 21 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Keweenaw

(County)

Located In:

Corner Code #

1. Public Land Survey

T 58N R 29W

I-11

T 58N R 29W

MC 14

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

REGISTER'S OFFICE

County of Keweenaw } SS

Received for Record, the 30th

day of December A.D. 19 97

at 10:00 o'clock A.M., and Recorded

in Liber 1 of LCR

on page 175

Julie Carlson, Deputy

Register of Deeds

Register of Deeds Stamp & File Number

I, John Haataja, in a field survey on 11/13, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-11 Wood post set in 1847
Cedar 10" S70°E 16LKS
Cedar 12' N55°W 23 LKS
C&H surveyor W. Kline placed an iron pin at this corner on October 6, 1952.

MC 14 Wood post set at 6' above watermark in 1847.
Y. Pine 12" S70°W 70LKS
Fir 6" North 21 LKS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-11 Found iron pin knocked over. Reestablished corner at record distance from pin at 1/16 corner to the East.

MC 14 No evidence of corner found. Set MC on Section line between Section 26 & 35 at high watermark.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-11 Set 1" pin with brass cap
4" Balsam N19°W 21.10'
6" W. Birch N85°E 18.31'
5" Balsam S47°E 10.48'
14" Cedar S19°W 48.62'

MC 14 Set 1" pipe with brass cap
12" Spruce S75°W 44.90'
15" Spruce N76°W 9.23'
10" Balsam N42°E 17.80'
12" Spruce N84°E 45.84'

Ratified by Peer Group
In accordance with P.A. 345
Co. Rep. [Signature]
Date 10/15/97

Signed by

Date 12/30/1997

Surveyor's Michigan License No. 19833

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

