SURVEY & REMONUMENTATION

JAN 2 1 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Keweenaw	•	•	REGISTE	R'S OFFR F 🚶 👵	2
(County)	Located In:	Corner Code ≠	County of	Removed Filt	3014
Public Land Survey .	58N R 29W T 58N R 29W T R	MC 17 MC 13	day of <u>D</u> at 10:00 in Liber	octocs A M. a	nd Recorded LCR
Property Controlling in Section	T R S T R S T R		on page	4 11/1/1/A/A/A/A/A/A/A/A/A/A/A/A/A/A/A/A/	ple by Dends
Miscellaneous Property in Sec.	S T R S T R		Register	of Deeds Stamp	& File Number
	Recorded Plat			BCDEF	G H I J K L I
		•	3	7 8 9 9	3 2 - 1 - 1 - 12 - 12 - 12 - 12 - 12 - 1
do hereby certify that under a in lines 1 and 2 above were current manual of survey ins Management or by a decree of above were in conformance were in conformance.	equirements of P.A. 74, Michigan P.A. In conformance with regulations a structions of the United States Depart a Court of Law and/or that the corresponding the P.A. The Property of the Michigan Board, re-established, monumented, re	A. of 1970, the corner points mand rules therefore as required in the Interior, Bureater points mentioned in lines of Land Surveyors or by a December 2015.	nentioned 6 ced in the 7 ced in the 3.4 and 5 cecree of a ceree of	-18	
NOTE: Not more than 4 on this certificate	corners, all in the same town a e.	and range, may be record	ied 11	-313233-	34 35 - 36
MC 17 Wood post se Y. Pine 10"	al monument and accessories at t in 1847 S66° W 83 LKS 63° W 107 LKS	MC 13 Wood pos Fir 10"	tion:		
		: :			
		•	•		
MC 17 Reestablishe in LCR 1, Pa Records. Ree line from Mo	r evidence found and/or method d in 1990 and recorded ge 87, Keweenaw County stablished MC and Sect numents as called for on of U.S. Lighthouse	MC 13 No Se ton co	eestablishing corn evidence of t MC set SO2° rner at the h e equivalent due South.	original com '-36'-16" E d nigh waterman	of Section ok which is
;				atified by Peer (ccordance with l	
			Date _	10/15/	67
C. Description of monur	ment for corner and accessories	s established to perpetua	te locating the pos	sition of the corne	er:
16" R. Pine : 16" R. Pine :	N17° W 35.79' S84° E 2.09'	12" W. Plat Mod	pipe with bra Pine N53° W 1 Pine S69° W 2 n. N23° E 132 n. N03° W 150	21.90 20.67 20.67 20.61 20.67	JOHN I. HAATAJA LAND SURVEYOR NO. 19833
	0 1/ 1		· ·	* 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	D LAND SULLED
Signed by	19833	Date	12/30/	1997	
Surveyer's Michigan Lice	nse No.		FORM APPROVED BY	MICHIGAN STATE BOARD OF	REVISED MAY 14, 19