

AUG 06 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Kalamazoo

(County)

Ross Twp.

Located In:

Corner Code #

1. Public Land Survey

T 1 S. R 9 W.

H-11

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

CLERK - REGISTER

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD
96 MAR 23 PM 1 47

LIBER

2 PAGE 009

Register of Deeds Stamp & File Number

I, Robert E. Snell, in a field survey on April 30, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1826: United States Government Surveyors; set 1/4 Section post.

Wh. Oak 20" S. 70° E. 6 lks.
Ironwood 6" N. 82° W. 22 lks.

1883: F. Hodgman, County Surveyor; found iron bar of resurvey at intersection of fences. No U.S. witnesses. Bored 3 ft. put iron bar in bottom with small stone and 2 foot earthen post over and marked.

Red Oak 14" N. 17° W. 8 lks.
Hickory 12" N. 87½° E. 57 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1960: Wilkins & Wheaton Engr. Co.; found tile.

20" Oak N. 87° W. 10.8'
10" Twin Oak N. 2° E. 53.9'

1996: Found tile at surface at fence intersection.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
5-16-1996

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-11: South 1/4 post Section 27, T. 1 S., R. 9 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on May 16, 1996, and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round tile. Placed remonumentation sleeve over tile.

PK Nail on North Side of 32" Oak N. 72° W. 11.30'
PK Nail on East Side of R.R. tie fence post N. 4° E. 14.78'
PK Nail on South Side of 4" Cherry Cluster N. 75° E. 38.47'
PK Nail on East Side of R.R. tie fence post South 0.58'
Centerline of 4" Cherry N. 28° E. 1.5'±

Signed by

Robert E. Snell

Date

5-23-96

Surveyor's Michigan License No.

9734