

SURVEY & REMONUMENTATION

FEB 18 1994

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD

'93 DEC 29 AM 11 22

RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in 10-6-93

KALAMAZOO
(County)

Located in:

Corner Code ##

ROSS TWP.

1. Public Land Survey

T 1 S R 9 W

K-9

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

James E. Young
CLERK-REGISTER

LIBER 1 PG 1050

Register of Deeds Stamp & File Number

I, GARY D. HAHN, in a field survey on OCTOBER 4, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner post established by U.S. Deputy Surveyor Thomas Whelpley, 1856.
Accessories: White Oak 18" S11°W 21 White Oak 16" N56°E 47

Resurvey by F. Hodgman, April 1869. "Long stone with point up and a small stone around it in the corner. Laid a large stone overall."

Accessories: Cherry 10 N79°45'E 1.70 Black Oak 10 S56°E 2.27 1/2.

Remonumentation by F. Hodgman, October 1883. "Found stone and witness trees of resurvey standing. The road has been raised so I put earthen post over the stone with stone around and marked. Accessory: Red Oak S57°1/2 E 16 Lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original corner with accessories not recovered.

Found 3/4" square bolt flush with asphalt. Under bolt (about 2' deep) found 2 1/2" galvanized pipe. Inside 2 1/2" pipe, found 3/4" galvanized pipe. Found small shards of earthen tile about 2 1/2 feet deep.

At 0.50' West and 0.80' South of bolt location, found long stone with point up surrounded by clay bricks all about 3 1/2 feet deep. Found solid clay tile with X on top standing erect under long stone at 4 1/2 feet deep believed to be same as called for in 1883 remonumentation by F. Hodgman.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-9 corner of sections 23, 24, 25, & 26, T 1 S - R 9 W, Ratified by Kalamazoo County Remonumentation program peer group on October 6, 1993. Found 3/4" square bolt flush with asphalt over 2 1/2" galvanized pipe with 3/4" galvanized pipe inside. Found small shards of earthen tile around galvanized pipes. At 0.50' West and 0.80' South of bolt location found long stone with point up surrounded by clay bricks at about 3 1/2' deep. Found solid clay tile with X on top standing erect under stone at 4 1/2' deep. Clay tile is believed to be same as called for in 1883 remonumentation by F. Hodgman and is accepted as a careful and faithful perpetuation of the original corner position. Removed long stone, clay bricks, galvanized pipes, clay shards, and square bolt. Placed 30" Harrison monument over solid clay tile with X on top and placed monument box over corner.

Accessories: Set p.k. nail in 6" Ash N30°W 51.80'

Set p.k. nail in 14" Oak S45°W 47.74'

Set p.k. nail in 19" Ash S25°W 63.92'

Set p.k. nail in R.R. tie fence post East 35.71'

Approximate centerline asphalt road East 2.4'

Signed by

Gary D. Hahn

Date 12-28-93

Surveyor's Michigan License No. 38116