REMONU	MENTATION O 0 8 2000	The control of the co			\bigcirc
For corners in Kalamazoo (County) Ross Township 1. Public Land Survey	Filing Req	RNER RECORDATION CERTIFuirement of Act 74, Mich. P.A Corner Code # L-11	FICATE 1. 1970		3
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR	CRANE LAND SURVEY	/ING LANDCOR-Kala	LC=00008 Page: 1 of 1 07/12/1999 10 Bk-2 Pg-461 of Deeds Stamp & File	
I. William K. Crane , in a P.A. 74, Michigan P.A. of 1: with regulations and rules th states Department of the In that the corner points ment Michigan Board of Land S monumented, recovered, four NOTE: Not more than 2 con this certificate.	syo, the corner points mentioned in linerefore as required in the current materior, Bureau of Land Management of tioned in lines 3, 4 and 5 above were surveyors or by a Decree of a Cound as expressed below:	o hereby state that under requirements ones 1 and 2 above were in conformance rual of survey instructions of the Unite or by a decree of a Court of Law and /c in conformance with the rules of the rit of Law; established, re-established in conformance with the rules of the rit of Law; established in the rule of Law; e	Se	D E F G H I J 5	12
G.L.O., December 1826, a 12" W. Oak N 10° E 8" Burr Oak S 62° V Field notes of A. H. Chase "South 1/4 post Sec. 2 River."	: 120 links V 48 links e for a 1929 survey of Fred Lamor	ra Farm in Section 25 indicate: or Barnett Maple at N 60° E 98 feet	t and 1175 feet So	uth of South Bank Kalar	mazoo
Brace post North Records of Kalamazoo Co 14" Locust S 84° E 12" Locust S 39° E	67.75' bunty Road Commission: 119 links 117 links	d 6" iron pipe filled with concrete wi	RA BY KALAM REMONI PEE	ATIFIED AZOO COUNT JMENTATION R GROUP -22-1999	Y
		in. Agrees with Dekeyser survey for			
C. Description of monume	ent for corner and accessories and	shiphed to manufacture to a state	*** ***		

C. of for corner and accessories established to perpetuate locating the position of the corner:

Found 6" diameter pipe as described above is accepted as the best available evidence of the position of the original corner. As existing corner marker is very substantial, no new marker was set.

48" Soft Maple 42" Soft Maple 6" Ash \$ 72° E 126.30 N 70° E N 20° E 95.95 79.30 8" Ash S 30° W 22.49 Centerline of road North 35'

Signed by

Date July 12, 1999

milliam K. CRANE SURVEYOR

William K. Crane, P.S.

Surveyor's Michigan License No. 29243