

RECEIVED

1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD

'95 OCT 19 PM 3 31

James J. J...
CLERK-REGISTER

LIBER 1 1362

Register of Deeds Stamp & File Number

For corners in ROSS TWP.
KALAMAZOO
(County)

Located In:

Corner Code #

1. Public Land Survey T 1 S R 9 W
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Section S T R

M-4

4. Lot No. , Recorded Plat
5. Private Claims

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Allen H. McMachen, field survey on May 16, 1994,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1826 - J. Mullet, D.S., Set Quarter Section Post
Y. Oak 17" S. 56° W. 62 lks. Dist.
Y. Oak 16" N. 23° W. 44 lks. Dist.

1883 - F. Hodgeman, C.S., Ran N. 24° E. 110 lks. from bearing tree by Pratt
to Stake with Stone around. Bored 3' Put broken crockery and small
stone in bottom and 2' Earthen Post over with Stone around and
marked.
Hickory 6" N. 24½° E. 91½ lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found drilled Stone in monument box. Removed box and Stone and excavated
3'x3'x3' deep and found nothing below Stone.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
3-16-95



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found drilled Stone is accepted as a careful and faithful reestablishment
of the position of the original corner. Placed Harrison monument and
monument box over, Witnesses:

Nail & Tab in E. Face 5" Maple N. 30° E. 49.68'
Nail & Tab in N. Face 36" Maple WEST 26.18'
Nail & Tab in E. Face 10" Hickory N. 25° W. 52.15'
"PK" Nail in W. Face of Power Pole N. 52° E. 70.32'

Signed by Allen H. McMachen
Surveyor's Michigan License No. 16935

Date 10/18/95