

SURVEY &
REMONUMENTATION

FEB 26 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Alamo Township
Kalamazoo
(County)

Located In:

Corner Code #

1. Public Land Survey	T	1S.	R	12W.	C-7
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____
6. IWM Job No. 30177

I, Allen H. McMachen, in a field survey on July 28, 19 97,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1829 - Robert Clark, Jr., D.S., "Set 1/4 Section post", Bl. Ash 22" N. 50° W. 1 lk., Wh. Ash 10" S. 33° E. 9 lks.

1873 - Ed Strong, C.S., "Found Stone"

1966 - P. McPherson (Co. Po. Co.), "Set 'T' iron from County Highway witnesses", T. Pole N.NE. 65.54', P.
Pole S.W. 53.32', P. Pole E.NE. 70.97', P. Pole E.SE. 45.10'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found "T" iron in monument box. All above mentioned accessories are now gone. Removed "T" iron and box and dug to
depth of 3 feet and found no further evidence of corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found "T" iron is accepted as the best available evidence of the position of the corner. "T" iron was
replaced with a Harrison Monument and Monument Box, Accessories:

Nail & Tab in Southwesterly side U. Pole S. 40° E. 45.3'
Nail & Tab in Northwesterly side U. Pole S. 40° W. 64.9'
Iron rod placed N. 40° W. 46.2'
Iron rod placed N. 45° E. 35.4'

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
8-21-1997



Signed by Allen H. McMachen
Surveyor's Michigan License No. 16935

Date 11/02/97

LIBER

CLERK - REGISTER

2 PAGE 231

97 NOV 19 PM 3 48

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD

Register of Deeds Stamp & File Number