

APR 27 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in ALAMO TWP.

KALAMAZOO
(County)

Located In:

Corner Code ~~##~~

1. Public Land Survey

T1 S R12 W

G-12

2. Property Controlling in Section

S _____ T _____ R _____

3. Miscellaneous Property in Se

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat

5. Private Claims

I, Allen H. McMachen, made a field survey on January 7, 1994

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Government - Oak 8" S. 45° E. 69 lks.

Oak 10" S. 62° W. 67 lks.

1885 - Ed Strong found Stone and Brick.

Apple 10" S. 8°-10' W. 1.7 CH.

Oak 20" N. 43° W. 105 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994 - Found large Stone with drill hole surrounded by Brick
4"-6" below ground surface.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
3-3-94



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Stone is accepted as a careful and faithful perpetuation of the original corner. Removed Stone and placed Harrison monument.
Accessories:

Nail & Tab in 5" White Pine N. 34° E. 63.31'

Nail & Tab in 14" Walnut EAST 24.47'

Nail & Tab in Power Pole S. 4° E. 21.19'

Nail & Tab in 6" Sassafras S. 87° E. 38.04'

3/4" Iron rod S. 43° W. 5.57'

Signed by

Date _____

Surveyor's Michigan License No.