

SURVEY & REMONUMENTATION

JUL 23 1997

COMMISSION

LIBER

2PAGE 120

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Alamo Twp.

Kalamazoo Located In: Corner Code #
(County)

1. Public Land Survey T1S R12W L-09
T R
T R
T R
T R

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

CLERK - REGISTER

Annally Brown

97 APR 7 AM 9 20

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert E. Snell, in a field survey on March 6, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP 2-27-1997

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:
1829: United States Government Surveyors; set 1/4 Section post.

W. Oak 18" S. 47 $\frac{1}{2}$ $^{\circ}$ W. 99 lks.
W. Oak 12" S. 35 $\frac{1}{2}$ $^{\circ}$ E. 76 lks.

1869: F. Hodgman, County Surveyor; "1/4 Section corner, found stake from one witness. Set stone with brick around and marked W. Oak 20", N. 37 $\frac{1}{4}$ $^{\circ}$ E. 52 lks." Mile measured along South line Section 24 = 79.98 ch. (5,278.68') 1/2 mile = 39.99 ch. (2,639.34')

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1959: Ingersoll, Watson & McMachen; North 1/4 post Section 25, found stone with "x". Set iron and monument box over stone. Measurement from N. 1/4 post to NW corner = 2,640.25'

1960: MSHD; chiseled stone, 25" Maple S. 64 $^{\circ}$ E. 28.65', 41" Oak S. 11 $\frac{1}{2}$ $^{\circ}$ W. 21:12', 21" Sassafras N. 03 $^{\circ}$ W. 38.28'

1978: Wilkins & Wheaton Engr. Co.; found iron in monument box. Measurement from S. 1/4 post Section 24 to SW corner = 2,639.50', from S 1/4 post to SE corner = 2,639.50'

1996: Found iron over stone in monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-09: South 1/4 post Section 24, T. 1 S., R. 12 W., ratified by the Kalamazoo County Remonumentation Program Peer Group on February 27, 1997 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found $\frac{1}{2}$ "x18" iron over stone with "x" in monument box as set in 1869 survey by F. Hodgman. Set 20" Harrison over stone in monument box.

Exist. Nail/Tab in North Side	28" Hickory	S. 60 $^{\circ}$ E.	36.38'
Exist. Nail/Tab in East Side	32" Sassafras	North	38.12'
Nail in West Side	50" Oak	S. 18 $^{\circ}$ W.	21.31'
Nail in West Side	14" Double Sassafras	N. 50 $^{\circ}$ E.	55.14'

Signed by

Robert E. Snell

Date

3-14-97

Surveyor's Michigan License No.

9734