

'94 APR 28 AM 9 12

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

KALAMAZOO

(County)

Located In:

Corner Code ##

Sec. 4, Charleston Twp.

1. Public Land Survey

T 2 S R 9 W

E-2

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

James E. Smith
CLERK - REGISTER

LIBER

1 PG 1146

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Robert E. Snell, in a field survey on February 7, 19 94,

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
1826-Original corner by U.S. Government Survey-Set $\frac{1}{4}$ Post.

Y. Oak 16" South 39° West 18 Lks

Wh. Oak 7" North 45° East 99 Lks

1883-F.Hodgeman, County Surveyor-Found stake at intersection of fences said by Davis to be corner. No Witness. Bored 3' put in 1' brick and stone and 2' earthen post over with stone around.

Burr Oak 10" North 80 $\frac{1}{2}$ ° West 32 Lks

Burr Oak 20" South 89° East 23 Lks

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3' round tile with "X" on top down about 6" with stone around.

18" Oak North 45° West 2.0' (1982 Witness)

North & South Fence West 5.0'

18" Hickory South 20° West 13.5'

Twin Oak East 44.5'

East & West Fence South 9.0'

R. E. Smith
**RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
3-3-94**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-2 West $\frac{1}{4}$ Post Section 4, T. 2 S., R. 9 W., ratified by Kalamazoo County Remonumentation Program Peer Group on March 3, 1994. Found 3" round tile with "X" and stone around as called for in 1883 remonumentation survey by F.Hodgeman and is accepted as a careful and faithful perpetuation of the original corner's position. Placed remonumentation sleeve over tile.

PK Nail in Southwest Side 20" Oak

PK Nail in East Side 20" Hickory

PK Nail in South Side S.Branch 18" Twin Oak

PK Nail in North Side 8" Oak

Fence to North

Fence to West

North 42° West 1.82'

South 28° West 13.13'

South 84° East 44.76'

South 30° East 44.80'

West 5.0'

South 9.0'

Signed by

Robert E. Snell

Date

4-27-94

Surveyor's Michigan License No.

9734