

SURVEY & REMONUMENTATION

JUL 23 1997

LIBER 2 PAGE 118

COMMISSION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Charleston Township
Kalamazoo Located In: Corner Code #
(County)

1. Public Land Survey	T <u>2S.</u> R <u>9W.</u>	<u>F-11</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
Property in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

CLERK - REGISTER

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD
JUL 20 PM 3 35

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Allen H. McMachen, in a field survey on January 24, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1826 - John Mullett, D.S., Set quarter Section post, Wh. Oak 10" N. 20° E. 18 lks., Wh. Oak 12" S. 15° W. 99 lks.

1869 - F. Hodgman, C.S., "Old Stake and witness standing"

1883 - F. Hodgman, C.S., "Found stake hole with stones around. Both U.S. bearing trees alive. Bored 3' and filled the bottom with small stones and put 2' earthen post over with stones around."

1995 - William Crane, L.L.S., L.C.R.C. L. 1, Pg. 1426 "Found clay tile 1'± below ground surface". Steel fence post, South 1'±, 24" Oak N. 30° E. 2.70', 24" Oak N. 10° E. 23.17', 2" Oak West 6.79'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found clay tile 1' below grade per 1995 witnesses. Tile is in a pile of field stone and has fence running North, South and East.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
2-27-1997

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found clay tile is accepted as a careful and faithful perpetuation of the position of the original corner. Brought tile to surface and applied a standard sleeve, Accessories:

Nail & Tab (found) on East side 24" Oak N. 10° E. 23.15'
Nail & Tab (found) on North side 24" Oak N. 30° E. 2.70'
Nail & Tab (found) on East side 10" Cherry S. 16° E. 19.38'
Base of steel fence post South 0.93'



Signed by Allen H. McMachen
Surveyor's Michigan License No. 16935

Date 3/18/97