

APR 01 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
COUNTY OF KALAMAZOO  
RECEIVED FOR RECORD

'96 JAN 23 PM 3 50

For corners in  
Kalamazoo  
(County)  
Oshtemo Twp.

Located In:

Corner Code #

1. Public Land Survey T 2 S. R 12 W. J-05  
T R  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Section S T R

*James P. Young*  
CLERK-REGISTER

LIBER 1 1431

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

I, Robert E. Snell, in a field survey on October 30, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1829: United States Government Survey; set 1/4 Section post.

Br. Oak 8" West 123 lks.  
Br. Oak 7" S 10° E. 93 lks.

1871: F. Hodgman, County Surveyor; found 1/4 Section corner stake from one living witness and stump of the other. Planted large stone with brick around.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1991: Wilkins & Wheaton Engineering Co., R. Snell; found stone and brick.

36" Oak N. 85° W. 30.5'  
36" Oak N. 55° E. 20.00'  
Dbl. 24" & 16" Oak N. 20° E. 20.50'

LCRC recorded in Liber 1, Page 492.

1995: Found stone with drill hole on high side of stone. Stone was at the surface near intersection of fences. Brick was found around the stone in line of stones to East.

RATIFIED  
BY KALAMAZOO COUNTY  
REMONUMENTATION  
PEER GROUP  
12-14-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-05: South 1/4 post Section 11, T. 2 S., R. 12 W., Ratified by Kalamazoo County Remonumentation Program Peer Group on December 14, 1995 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found stone with drill mark and brick around as called for in 1871 survey by F. Hodgman, County Surveyor. Removed stone and placed a 30" Harrison Monument, left brick around monument.

Nail/Tab in W. side Dbl. 26" and 15" Oak N. 26° E. 21.17'  
PK Nail in S. side 30" Oak N. 80° E. 19.09'  
Nail/Tab in W. side Twin 24" Cherry S. 06° W. 47.58'  
Nail/Tab in N. side 42" Oak N. 82° W. 30.42'

Signed by *Robert E. Snell*

Date *1-18-96*

Surveyor's Michigan License No. 9734