OCT 0 6 1997	
COMMISSION	
LAND CORNER RECORDATION CERTIFICATE LIBER 294GE 154 Filing Requirement of Act 74, Mich. P.A. 1970	
For corners in Climax Twp.	
Kalamazoo Located In: Corner Code #	
1. Public Land Survey T_3S_R_9W B-11	
T R T R T R T R T R T R T R T R T R T R	
	-
4. Lot No, Recorded Plat	М
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	1
11	_
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	
A. Description of original monument and accessories and/or subsequent restoration: 1825: United States Government Surveyors; set 1/4 Section post.	
Beech 8" N. 14° E. 22 lks.	
<ul> <li>Wh. Ash 10" S. 27° W. 7 lks.</li> <li>1875: F. Hodgman, County Surveyor; "Found old stake with stone around. Set marked stone.</li> </ul>	
Cherry 6" N. 49°-40' E. 74 3/41ks., W. Ash 6" S. 73°-30' E. 128 lks."	
1883: F. Hodgman, County Surveyor; "Replaced stone of resurvey with 3 ft. earthern post and noted new witness. Maple 3" North 42 lks."	-
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
1940: Wilkins & Wheaton Engineering Co.; Found tile down 30", set iron above.  18" Elm North 38.15' C// RATIFIED	
6" Walnut S. 35° E. 40.4' // BY KALAMAZOO COUNTY	
18" Maple N. 35° E. 41.5' REMONUMENTATION 12" Walnut S. 55° W. 38.9' PEER GROUP 7-16-1997	
1997: Found PK Nail under 3" of bituminous paving. Found 1/2" iron 9" below surface (18" lo Found tile down 40" below surface. (From 1940 Walnut trees witnesses, see above).	ong).
round the down to below suitable. (Floid 13to Mathial trees withesses, see above).	
C. Description of monument-for corner and accessories established to perpetuate locating the position of the corner: \$\frac{1}{2}\$ B-11: South 1/4 post, Section 30, T. 3 S., R. 9 W., ratified by the Kalamazoo County Remonumentation Program Peer Group on July 16, 1997 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round tile wit "x" on top 40" below surface. Tile was set in 1883 remonumentation survey by F. Hodgm County Surveyor. Set 20" Harrison Monument to within 3" of surface and placed monumer box over.	nan,
PK Nail in East Side 36" Maple N. 56° E. 42.30' PK Nail in West Side 28" Walnut S. 32° E. 41.83'	
PK Nail in East Side Power Pole S. 40° W. 66.90' PK Nail in West Side 26" Walnut S. 58° W. 39.39'	
Signed by	