

# SURVEY & REMONUMENTATION

APR 27 1995

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
COUNTY OF KALAMAZOO  
RECEIVED FOR RECORD

'94 DEC 6 PM 3 56

For corners in

Kalamazoo

(County)

Climax Township

1. Public Land Survey

Located In:

Corner Code #

T 3 S R 9 W

E-10

T R

T R

T R

S T R

S T R

S T R

S T R

2. Property Controlling  
in Section

3. Miscellaneous

Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

*James J. Gump*

CLERK-REGISTER

LIBER

1 PG 1191

Register of Deeds Stamp & File Number

I, Robert E. Snell, in a field survey on March 3, 19 94

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1825: U.S. Government Survey; Set 1/4 Section Post

Beech 30" South 10½ Lks  
Beech 8" North 44° East 19 Lks

1874: F. Hodgeman, County Surveyor; Found old stake, set pointed stone, marked:

Beech 12" North 10° East 30½ Lks  
Maple 6" North 71° West 41 Lks

1885: F. Hodgeman, County Surveyor; Found stone and witness trees of resurvey staking. Set 3' earthen tile.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found two 1' tiles, one on either side of a railroad rail fence post. Rail is 4' above ground and in good shape (no rust). Apparently tiles were removed in process of placing rail. 1959 witness say found tile wired to "T" rail fence corner. Fence East and West.

RATIFIED  
BY KALAMAZOO COUNTY  
REMONUMENTATION  
PEER GROUP  
11/17/94 R.E. Gump

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-10 West 1/4 Post Section 28, T. 3 S., R. 9 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on November 17, 1994 and is accepted as a careful and faithful perpetuation of the original corner's position. Found 2' of 3" round tile tied to either side (North and South) of 4' high Railroad Rail Fence Post.

PK Nail in West Side 12" Walnut North 26° East 30.23' in East and West Fence  
PK Nail in South Side 10" Poplar North 80° East 52.75'  
PK Nail in West Side 4" Beach North 30° East 50.10'  
PK Nail in West Side 6" Elm North 45° East 25.85'

The Section of Railroad Rail has been accepted as the corner and no Harrison monument was placed.

Signed by

Date

Surveyor's Michigan License No.

9734