OCT 0 6 2007

-1	991 9 9 133/
2	COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Climax Township

KALAMAZ00 Located In: Corner Code # 1. Public Land Survey T_3S_R_ 2. Property Controlling in Section 3. Miscellaneous Property in Sec.


16 STATE OF MICHIGAN
LCOUNTY OF KALAMAZOO
RECEIVED FOR RECORD LIBER

Register of Deeds Stamp & File Number

4. Lot No	, Recorded Plat	
5. Private Claims		
e. i mate Olamia		NS

Robert E. Snell , in a field survey on May 29, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

1825: United States Government Surveyors; Set 1/4 Section Post.

White Oak 12" 0 1/2° West North 35 Lks 10" White Oak North 50 1/2° West 43 Lks

F. Hodgman, County Surveyor; "Ran South 50 1/2" East, 43 Lks from stump of U.S. bearing 1883: tree to old stake. Bored 3 feet. Put brick in the bottom and 2 1/2 feet of earthen post over with stone around and marked for new bearings, White Oak 12" Dia., North-

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" x 18" Iron rod along West side of 3" round tile. Top: of tile broken off and down 16" below surface of road with large stones around. Found bent iron rod, 12.25' to South, believed to represent East 1/4 Post, Section 31, T. 3 S., R. 8 W., (U.S. Surveyors intersected East County Line, 36 Lks South of Post, 1/2 Mile North).

RATIFIED REMONUMENTATION PEER GROUP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. M-12 East 1/4 Post Section 36, T. 3 S., R. 9 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on June 19, 1997 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round tile down 16" with top broken off and 3/4" x 18" iron rod along West side of tile. Tile was set in 1883 remonumentation survey by F. Hodgman, County Surveyor. Placed 12" of 18" Harrison Monument and

3/4" x 18" Iron Rod (with Red Cap) Capped Iron (C.L.S.#29243)

North 60° East 36.60'

South 60° West 45.12' PK Nail in South Side 12" W. Cherry North 56° West 56.82' PK Nail in South Side 4" x 4" Wood Post (Tel. Cable marker) North 34° West 49.25'

Surveyor's Michigan License No.