

SURVEY & REMONUMENTATION

FEB 26 1998

7-2 SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Pavilion Twp.
Kalamazoo
(County)

Located In:

Corner Code #

1. Public Land Survey	T	3S.	R	10W.	G-7
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S		T	R	
	S		T	R	
3. Miscellaneous Property in Section	S		T	R	
	S		T	R	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Allen H. McMachen, in a field survey on November 11, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1827 - Robert Clark, Jr., D.S.

Set post corner to Section 15, 16, 21 & 22, Br. Oak 8" S. 18° E. 35 lks., Elm 10" N. 48° E. 57 lks.

3/1874 - F. Hodgman, Surveyor, "Marked Elm 6" S. 58° W. 91 lks."

4/1874 - F. Hodgman, Surveyor, "Stake in crossway by former survey & one witness."

1888 - F. Hodgman, C.S., "Found stake & stone N. 18° W. 35 lks. from Burr Oak bearing tree. Set post."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found monument box 6" below surface containing an iron rod. Removed box and iron and dug to depth of 3' finding clay tile directly below iron location.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found clay tile is accepted a careful and faithful perpetuation of the position of the original corner. Placed 30" Harrison Monument over found clay tile with monument box over, Accessories:

Nail (existing) in Easterly side of P. Pole N. 05° W. 56.52'
Nail (existing) in Triple 30" Maple S. 70° W. 95.3'
Inside corner of bridge N. 65° E. 34.0'
Inside corner of bridge S. 55° E. 26.1'

Signed by Allen H. McMachen
Surveyor's Michigan License No. 16935

Date 12/22/97

LIBER 2PAGE 262

CLERK - REGISTER

Handwritten signature

97 DEC 22 PM 3 49

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
12-18-1997

