

SURVEY & REMONUMENTATION

APR 27 1995

LIBER

1 PG 1160

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Kalamazoo

(County)

Texas Township

Located In:

Corner Code #

1. Public Land Survey

T 3S R 12W

E-3

2. Property Controlling in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

CLERK - REGISTER

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD
94 JUL 6 AM 11 52

Register of Deeds Stamp & File Number

Thomas W.

I, Chettleburgh, in a field survey on March 22, 1994

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner Post set by U.S. Government Deputy Surveyor Thom Whelpley, 1829.

Accessories: S31 1/4°W W.Oak 12" .06, N58°W W.Oak 8" .25.

Kalamazoo County Witness Sheet, 1943, Large stone with small stones around MDOT 1962, 1/2" iron bar.

Accessories: Railroad tie fence corner South 35.1'.

T. Chettleburgh, 1988, Found 3/8" iron bar in monument box, recorded LCRC Liber 1, Page 885.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original Corner Post & Accessories not recovered.

Found 3/8" iron bar in monument box in centerline E-W road directly over drill stone 1.3' deep, checks corner location as described by MDOT and as described and recorded by T. Chettleburgh.

The 3/8" iron bar and drill stone was accepted as a careful and faithful perpetuation of the position of the original corner and was ratified by the Kalamazoo County Remonumentation Program Peer Group on April 21, 1994.

Set 15" Harrison Monument and monument box directly over the found drill stone.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
4-21-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

15" Harrison Monument in monument box.

Nail/Tag	NE side	10" Oak	S60°E
Nail/Tag	W side	Triple 15" Oak	S16°E
Nail/Tag	SE side	16" Hickory	S37°W
Nail/Tag	N side	13", 20" Tw.Oak	S69°W
Nail/Tag	S side	20" Oak	N65°W

83.62'
39.53'
32.31'
61.18'
74.02'



Signed by Thomas W. Chettleburgh Date July 5, 1994

Surveyor's Michigan License No. 16036