## SURVEY & REMONUMENTATION

APR 27 1995

1 PG 1156 LIBER

COMMISSION

AND CODNED DECORDATION CERTIES

C.C. Marian		ement of Act 74, Mich. P		LEKA	7.		1		
or corners in					: (5)		တ	T. 7.	
Kalamazoo	Located In:	Corner Code ##		7	ري م ري	Ď	H <sub>1</sub>	¥ ₹	
Texas Township					CISTER		711	REA	: E
. Public Land Survey	т <u>3S</u> R <u>12W</u>	<u>G-1</u>			4	Š		00 7	3 A
	T R	<del></del>			20 `	Ę	57		700 200
						/			
	ŢR								
. Property Controlling	S T R				•				
in Section	S T R								
. Miscellaneous	S T R		Register	of De	eds S	stamo	& File	Numbe	÷r
Property in Sec.	S T R								
. Lot No, F	Recorded Plat					<b>.</b> .	с u		
. Private Claims			Î		<u> </u>	-	<del>                                     </del>	$\dot{1}$	
,	·		2	- 6	- 5-	<del> </del>	<b>┼</b> -┇—	<del> </del>	⊢┆┤
		•	3			<b>├</b>	+	$\bot$	
Thomas W.			4		8	 	10—		12
Chettleburgh	, in a field survey onM	March 22 1994	5	j	Ĭ	ľ	Ιĩ		
	quirements of P.A. 74, Michigan P.A.		ioned				TT		

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

Description of original monument and accessories and/or subsequent restoration:

Corner Post set by U.S. Government Deputy Surveyor Thom Whelpley, 1829.

Accessories: Bl Oak 16" S47°E .41, Bl. Oak 14" S79 1/2°W 1.00, falling 147 lks (97.02'),

Ed Strong, 1913, found original witness tree (stump), set stone, found stone at SE Cor. Sec. 33, T2S, R12W, measure falling at 190 lks (125.40'),

Kalamazoo County Witness Sheet, stone 1' below.

McMachen, 1977, Found 1/4" iron, Recorded LCRC, Liber 1, Page 756.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original corner post and accessories not recovered.

Found stone set by Ed Strong, 1913, 2.2' deep & 125.4' East of the SE Cor. Sec. 33, T2S, R12W.

Found 1/4" iron, as recorded by McMachen, 28.74' West of stone.

Found 5/8" iron 25.84' West of stone.

The found stone, as set by Ed Strong, was accepted as a careful and faithful perpetuation of the position of the original corner and was ratified by the Kalamazoo County Remonumentation Program Peer Group on April 21, 1994.

Date

Set 20" Harrison Monument and monument box directly over found stone,

RATIFIED SE Cor. Sec. 33, T2S, R12W West 125.40', Township line South 0.78'. BY KALAMAZOO COUNTY **REMONUMENTATION** PEER GROU 4-21-94

tion of monument for corner and accessories established to perpetuate locating the position of the corner 20" Harrison Monument in monument abox

4" Diameter Harrison Monument (SE Cor. Sec. 33, T2S, R12W) N87°W 125.40' Spike NW side 10" Oak N56°E 51.17 Spike NE side 18" Oak S58°E 66.74 S7°W Spike E side 20" Basswood 38.17' Centerline E-W road 1.5 North

THOMAS W. CHETTLEBURGH LAND JRVEYOR NO 16036

16036 Surveyor's Michigan License No.

Iulv 5, 1994