

APR 6 1 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
KALAMAZOO
(County)

Located In:

Corner Code #

TEXAS TWP.

- | | | | | | | |
|---|---|----|---|----|---|----|
| 1. Public Land Survey | T | 3S | R | 12 | W | G9 |
| | T | | R | | | |
| | T | | R | | | |
| | T | | R | | | |
| 2. Property Controlling
in Section | S | | T | | R | |
| | S | | T | | R | |
| 3. Miscellaneous
Property in Section | S | | T | | R | |
| | S | | T | | R | |
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD

'95 DEC 8 AM 10 55

James D. Young
CLERK-REGISTER

LIBER 1 1405

Register of Deeds Stamp & File Number

I, GARY D. HAHN, in a field survey on MAY 2, 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

- 1829 Corner post established by U.S. Deputy Surveyor E. H. Lytle
Accessories: W. Oak 14 in S17°E 12 lks. W. Oak 16 in N6°W 42 lks.
- 1870 F. Hodgman Co. Sur. "Found sec. cor. stake from one witness dead planted stake and
marked stone from which bear Hickory 10 S89½°W 1.05½ Hickory 10 S19½°E 2.22"
- 1872 S. Hodgman D.C.S. "stone"
- 1973 Dennis Middleton LCRC Liber 1, Page 381 "Mon. box & 1" iron bar" 40" Oak S-SW 29.9' to 60d
nail 60" Oak North 28.82' to 60d nail 24" Hickory NW 35.16' to 60d nail.
- 1977 Allen McMachen RLS16935 LCRC Liber 1, Page 752 "Fnd. iron" 48" Oak N10°E 28.61'
36" Oak S20°W 28.93' 15" Hickory N40°W 59.25'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories not recovered.

Found 5/8" dia. 24" long rebar in mon. box below asphalt road.'

Found 4.5" x 7" x 11" pointed stone 10" below surface directly below rebar in box.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
6-15-95 *R.D.H.*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G9, Southeast corner Section 21, T3S, R12W, Ratified by Kalamazoo County Remonumentation
Peer Group on June 15, 1995. The location of the Stone and Rebar is accepted as a careful
and faithful perpetuation of the position of the original corner. Removed rebar and stone
and replaced with a 20" Harrison Monument in mon. box.

- Fnd. nail with tab in 52" Oak N10°E 28.68'
Set P.K. nail in 3" Oak S42°E 37.10'
Fnd. P.K. nail in 24" Oak N38°W 35.28'
Fnd. cabin spike in W. side 38" oak S22°W 28.90'
Fnd. cabin spike in E. side 38" Oak S22°W 27.78'

Signed by

Gary D. Hahn

Date 8-31-95

Surveyor's Michigan License No. 38116

