FEB 08 1999

LIBER

1	SE	CTION					
	<i>(</i>	LAND C	ORNER RECORDATION	CERTIFICATE		•	
For	r corners in	70 1441	equirement of Act 74, M	ich. P.A. 1970			<u>.</u>
_	KALAMAZ (County)	ZOO_ Located In:	Corner Code #	•	CLERK	DEC 15	
1.	Public Land Survey	T <u>3S.</u> R T R T R			- REGISTER	F KALAMA FOR REC 5 PM 3	F MICHIC
2.	Property Controlling in Section	ST R ST R			E &	1200 20RD 50	Ž
3.	Miscellaneous Property in Section	S T R S T R		Registe	of Deeds S	tamp & File Nun	nber
		Recorded Plat	•		A B C D	E F G H I	J K L I
6	. IWM Job No. 24130			. 2 3 4	6 5 -7 -8 -	9101	2 - 1 1 1 1 1 1 1 1 1 1

as expressed below: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found

Corner not placed by original government surveyors.

1953 - Wilkins & Wheaton, Measured from Center quarter corner to West quarter corner at 2623.79 feet.

September

1960 - W.D. Ingersoll, R.L.S., "Found pipe - Nothing beneath", North 35.54 14 Red Oak,, East 61.10 30 Wh.

Oak, South 32.651 1811 Red Oak.

I. Allen H. McMachen , in a field survey on .

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" I.D. pipe per 1960 information. Pipe is on line between W1/4 corner (standard marker) and E1/4 corner (standard marker). Pipe is ±2' West of a line between N1/4 corner (standard marker) and S1/4 corner (standard marker). Distance between Center quarter corner (pipe) and W1/4 corner (standard marker) was measured at 2623.91'.

> RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 10-15-1998

2page 390

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

This corner not established by original government surveyors. Found pipe is accepted as the best available evidence of the position of the corner. Replaced pipe with a 30° Harrison Monument, Accessories:

Nail & Tab in West side 10" Twin Oak N. 30° E. 12.42' Nail & Tab in South side 10" Twin Cherry East 10.01' Nail & Tab in S.W. side 14" Oak S. 52° E. 25.87' Nail & Tab in West side 10" Cherry S. 05° E. 23.80 In stockade fence North and South

Signed by

PROFESSIONAL

CHIGAN STATE ROARD OF PROFESSIONAL SURVEYORS JAN 28, 1971

ALLEN H. McMACHEN

PROFESSIONAL

SURVEYOR

No.

16935

EVISED MAY 14, 1975 REVISED JAN., 1983

Surveyor's Michigan License No.