

# SURVEY & REMONUMENTATION

SEP 14 1998

SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Texas Township  
Kalamazoo (County)

Located In:

Corner Code #

- |                                    |   |     |   |      |      |
|------------------------------------|---|-----|---|------|------|
| 1. Public Land Survey              | T | 3S. | R | 12W. | J-13 |
|                                    | T |     | R |      |      |
|                                    | T |     | R |      |      |
|                                    | T |     | R |      |      |
| 2. Property Controlling in Section | S | T   | R |      |      |
|                                    | S | T   | R |      |      |
| 3. Miscellaneous                   | S | T   | R |      |      |
| Property in Section                | S | T   | R |      |      |

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Allen H. McMachen, in a field survey on September 29, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

### A. Description of original monument and accessories and/or subsequent restoration:

1829 - E. H. Lytle, D.S., Set quarter Section post, Wh. Ash 7" N. 63 $\frac{3}{4}$ ° E. 20 lks., Bl. Walnut 18" N. 1° W. 44 lks.

### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found stone with "X" at South end of fence to North. Measure West 2642.72' to standard marker at Southwest corner, Section 35, Texas Township. Also meas. East 2648.87' to iron at Southeast corner, Section 35, Texas Township.

### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found stone with "X" is accepted as the best available evidence of the position of the corner. Removed stone with "X" and replaced with a 30" Harrison Monument. Buried stone on East side of monument with "X" to the side, Accessories:

Nail & Tab in 20" Oak North 4.51'  
Nail & Tab in North side 16" Elm N. 75° E. 33.55'  
Nail & Tab in South side 18" Elm East 34.72'  
Harrison Monument at North quarter corner, Sec 2, Prairie Ronde West 49.83'  
Fence to East is North 3'

Signed by Allen H. McMachen  
Surveyor's Michigan License No. 16935

Date 2/24/98

**RATIFIED  
BY KALAMAZOO COUNTY  
REMONUMENTATION  
PEER GROUP**  
11-20-1997

