

Sequence #2



LC-000106

Page: 1 of 1

12/30/1999 01:58P

Bk-2 Pg-559

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Kalamazoo
(County)

Located In:

Corner Code#

Wakeshma Township
1. Public Land Survey

T 4S R 9W E7
T R
T R
T R
S T R
S T R
S T R
S T R

2. Property Controlling
in Section
3. Miscellaneous
Property in Sec.

4. Lot No. , Recorded Plat
5. Private Claims

SURVEY &
REMONUMENTATION

FEB 08 2000

SECTION

Register of Deeds Stamp & File Number

I, Gary D. Hahn, in a field survey on October 29, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	13		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

1826 - Corner established by U.S. Deputy Surveyor, Robert Clark, Jr. Beech 13 in. S 78° W 12 lks.
Beech 5 in. N 26½° E 10 lks.

1872 - Samuel Hodgeman: "Stone with drill hole + side stones N+S 50 lks."

KCRC Witness Tie Book: (W) Map. 24" N 2° W 29.05'
(W) Map. 16" N 35° W 35.55'
(W) Map. 20" S 15° E 26.65'
(W) Stone set 33' North + South.
(W) Drilled stone by an (H)
NE. Cor. Hse. 52.25'
NW. Cor. Hse. 70.06'

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
12-17-1998

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories not recovered. No surface monument found. Excavated a 7' (N+S) x 17' (E+W) x 7' deep hole centered on the bisection of a line between corners E7 and G7. Found no evidence of stone w/drill hole. Area may have been excavated for road. Side stone to the north gone due to fiber optic installation. Side stone to the south gone due to driveway cut.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F7, South Quarter Post of Section 16, Town 4 South, Range 9 West. Ratified by the Kalamazoo County Remonumentation Peer Group on December 17, 1998. The position of the bisection of the line between corners E7 and G7 is accepted as a careful and faithful reestablishment of the position of the original corner. Set a 30" Harrison Monument in a mon. box at said bisection.

Witness Ties: Set Mag Nail in NE. side P.P. S 50° E 41.90'
SW corner of house foundation N 40° W 69.43'
Found 4" x 8" flat stone 1 - 2 inches below sod North 31.97'
Set Mag Nail in NW face 15" Pine S 60° W 65.33'



Signed by Gary D. Hahn
Surveyor's Michigan License No. 38116

Date 10/30/99

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS,
JAN. 28, 1971

REVISED MAY 14, 1975
REVISED JAN., 1983 REVISED OCT., 1995