

SURVEY &  
REMONUMENTATION

1  
2  
AUG 22 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SCHOOLCRAFT TWP.  
KALAMAZOO Located in:  
(County)

Corner Code #

STATE OF MICHIGAN  
COUNTY OF KALAMAZOO  
RECEIVED FOR RECORD

'95 FEB 9 PM 3 58

*James J. Jones*

CLERK-REGISTER

LIBER 1 PG 1269

Register of Deeds Stamp & File Number

1. Public Land Survey T 4 S R 11 W D-4  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Section S T R

4. Lot No. , Recorded Plat  
5. Private Claims

I, Allen H. McMachen field survey on November 30, 1994,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found  
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original Government Survey did not set center, no historic information  
was found.

1962 - IWM set  $\frac{1}{2}$ " iron rod at intersection of  $\frac{1}{4}$  lines. (Job No. 1381-62)  
 $N\frac{1}{4}$ ,  $S\frac{1}{4}$ ,  $E\frac{1}{4}$ , &  $W\frac{1}{4}$  corners were all occupied by Tiles.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found  $\frac{1}{2}$ " iron rod per witnesses taken for 1962 IWM survey.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

This position not established by original Government Surveyor's.  $\frac{1}{2}$ " iron  
is accepted as the best available evidence of the position of the corner.  
Removed iron and placed Harrison monument. Accessories:

Nail & Tab in 16" Oak S.  $75^\circ$  E. 35.30'  
Nail & Tab in 30" Oak S.  $30^\circ$  E. 4.64'  
Nail & Tab in 13" Oak SOUTH 5.39'  
Nail & Tab in 30" Cherry S.  $75^\circ$  W. 34.03'

Signed by *Allen H. McMachen*

Date 2/9/95

Surveyor's Michigan License No. 16935

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN, 1983

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7			8		9		10		11		12	
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

RATIFIED  
BY KALAMAZOO COUNTY  
REMONUMENTATION  
PEER GROUP

