	SURVEY & REMONUMENTATION				
	NOV 2 5 1998	Sand of	Marie de la compansión de	facusanight	
	SECTION LAND CORNER RECORDATION CERTIFIE	104 TF		RECEIVED	ATS
For co	Filling Requirement of Act 74, Mich. P.A.	1970	OLERK	IN S	マイ マイ マ つ つ
	l ama zoc Located In: Corner Code #		- R &	£_3	-1-4 4-7-1
1. Pub	T4S R 11W G-08 T R T R		GISTER	- 8	KALAMAZOO
in So 3. Miso	perty Controlling S T R		IBER 2PAG	SE 356	
4. Lot i 5. Priva	No, Recorded Platate Claims				
I, Robinequirements Conformation United States United States United States Sound of	nents of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in tates Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, found as expressed below:	5 -18-7	8 9 9 17 16 1 16 1 16 1 16 1 16 1 16 1 16	H I J -3 -210 -1115 -14 -	K L 1
NOTE:	Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	8 —19— 9 —30— 11 —12—31—	-29 - 28 - 32 - 33 - 32 - 33 - 33 - 33 - 33	22 23 -27 26 - -34 35	24- 25- 36
A. Desc 1826:	cription of original monument and accessories and/or subsequent restoration:	13			<u> </u>
1020.	United States Government Surveyors; set 1/4 Section post Burr Oak 6" S. ½0 W. 192 lks. Burr Oak 18" N. 86 E. 442 lks.	t.			
1889:		ey in pl	ace, in lir	e with	
B. Desc 1942:	cription of corner evidence found and/or method applied in restoring or reestablishing corr Wilkins & Wheaton Engr. Co.; found tile, in line with fe center line of North and South Road, 12" Walnut S. 30° E 33.2', Fence East 32.5', Fence West 26.1'.	T	and 4' Wes	t of . 89 ⁰ E.	
1998:		box,∂äl le 3' be	so found ½". low surface	x12% îrûi , 3" rou	äà∍:: nd
	BY A	CALAMA	TIFIED 200 COU MENTATIO	INTY E	8
	East 1/4 post, Section 21, T. 4 S., R. 11 W., ratified by Remonumentation Program Peer Group on June 11, 1998 and faithful perpetuation of the position of the original conwith "x" on top 3' below surface of road with two, 1" incomposed by F. Hodgman, County Surveyor in a 18 Placed a 20" Harrison monument over tile in the monument 1/2" iron/cap in North Side Double Head Nail/Tab in West Side Nail/Tab in West Side 1/2" iron with Red Cap on West Edge of Pavement	PEER ition of the co y the Ka is accept rner. Fo ons above 389 Remor box. S. nut S.	GROUP orner: lamazoo Count ted as a can ound a 3" ro it in a mo numentation 84° E. 16° E.	nty reful and cound tile	d e
Signed by _ Surveyor's !	Michigan License No. 9734 Date	- 22	7-98		