

SURVEY & REMONUMENTATION

SEP 14 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Schoolcraft Twp.

Kalamazoo
(County)

Located In:

Corner Code #

1. Public Land Survey

T4S R11W

I-08

T R

T R

T R

T R

2. Property Controlling in Section

S

T R

S

T R

3. Miscellaneous Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Robert E. Snell, in a field survey on May 18, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP 6-11-1998

A. Description of original monument and accessories and/or subsequent restoration:

1826: United States Government Surveyor's; set 1/4 Section post.

Burr Oak 14" N. 37 1/4° W. 144 lks.

Burr Oak 13" N. 36 1/2° W. 260 lks.

1889: F. Hodgman, County Surveyor; "Found stone with brick under it on line with fences East and West. Set post."

Maple 1 1/2" N. 87° W. 29 lks.

Cherry 10" N. 29° E. 105 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1942: Wilkins & Wheaton Engr. Co.; found tile, down 14", top section gone. Placed iron in center line of road to South and in line with fence to East.

14" Cherry S. 88° E. 109.35'

8" B. Walnut N. 50° W. 28.3'

12" Cherry S. 15° W. 94.7'

1998: Found 3/8" x 15" iron in monument box with 4" round tile 2.0' below road surface.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-08: East 1/4 post, Section 22, T. 4 S., R. 11 W., ratified June 11, 1998 by the Kalamazoo County Remonumentation Program Peer Group and is accepted as a careful and faithful perpetuation of the position of the original corner. Found a 3/8" x 15" iron over 4" round tile in a monument box. Tile was set by F. Hodgman, County Surveyor in a 1889 Remonumentation Survey. Placed Remonumentation sleeve and 18" Harrison monument over tile in monument box.

Southeast corner "Z" Steel Post N. 60° E. 30.83'

Nail/Tab in South Side Power Pole S. 84° E. 86.98'

PK Nail over Nail/Tab in East Side W. Cherry S. 24° W. 95.92'

Nail/Tab in North Side Wood Fence Corner Post N. 86° W. 23.75'

Signed by Robert E. Snell

Date 9-2-98

Surveyor's Michigan License No. 9734

CLERK - REGISTER

SEP 3 PM 3 26

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD

LIBER 2 PAGE 317

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													