

SURVEY &  
REMONUMENTATION

APR 27 1995

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
COUNTY OF KALAMAZOO  
RECEIVED FOR RECORD

94 DEC 14 PM 2 39

For corners in COMMISSION

Kalamazoo

(County)

Located In:

Corner Code #

Schoolcraft Township

1. Public Land Survey

T 4 S R 11 W

K-11

T R

T R

T R

2. Property Controlling

S T R

in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

*James E. Snell*

CLERK-REGISTER

LIBER

1 PG 1211

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Robert E. Snell, in a field survey on May 18, 19 94

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1826: U.S. Government Survey; Set Post. Corner to Sections 25, 26, 35 and 36.

Tamarack	10"	South	71½°	West	45½ Lks
Bl. Ash	10"	South	88°	East	37 Lks

1889: F. Hodgman, County Surveyor; Found stone and Tamarack bearing tree, 12" North 04° West, 141 Lks in place. Set Post.

Black Ash	8"	North	72°	West	73 Lks
-----------	----	-------	-----	------	--------

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found 5/8" x 30" pipe at surface. Found stone and tile 3.3' below iron pipe.

RATIFIED

BY KALAMAZOO COUNTY

REMONUMENTATION

PEER GROUP

7-21-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-11 Southwest Corner Section 25, T. 4 S., R. 11 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on July 21, 1994. Found 3" round tile as called for in 1889 remonumentation survey by F. Hodgman and is accepted as a careful and faithful perpetuation of the position of the original corner. Placed 20" Harrison monument and monument box over tile at surface.

Exist. Nail/Tab in North Side	Power Pole	North 58° West	47.50'
Exist. Nail in South Side	15" Oak	North 61° East	66.57'
Exist. Nail/Tab in North Side	22" Oak	South 36° West	53.00'
PK Nail in East Side	28" Oak	South 05° West	60.20'
CL "Y" Avenue		South	11.00'

Signed by

*Robert E. Snell*

Date

12-14-94

Surveyor's Michigan License No.

9734