

# SURVEY & REMONUMENTATION

SEP 17 1999

## KALAMAZOO COUNTY REMONUMENTATION

### LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
COUNTY OF KALAMAZOO  
RECEIVED FOR RECORD

'93 NOV 11 AM 8 54

### SECTION

For corners in

Kalamazoo

County

Located In:

Corner Code #

1. Public Land Survey

T 4S R 12W

C-1 #001

T R

South Witness

T R

for NW Cor.

T R

Sec. 5

2. Property Controlling in Section

S T R

Prairie Ronde

S T R

Township

3. Miscellaneous Property in Sec.

S T R

S T R

*James J. Gump*  
CLERK-REGISTER

LIBER

1 PG 1016

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Thomas W.

Chettleburgh

in a field survey on October 15 19 93

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Corner falls in Paw Paw Lake

GLO April 7, 1827, ran Township line across Lake, set meander corners

GLO December 26, 1829, ran North between Section 5 & 6, set meander corner

Jay White 1955, Surveyed Nemedi's Unrecorded Plat,

Northwest and Southwest corners of Plat on West line of Section 5

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron pipe in concrete at Southwest corner of Nemedi's Unrecorded Plat, established plat corner as South witness point for the NW corner of Section 5

Replace iron pipe with 4" X 30" Harrison Monument.

W 1/4 Corner Section 5 S01°19'19"W 2366.04'

NW Corner Section 5 N01°19'19"E 515.04'

South shore Paw Paw Lake North 200' ±

**RATIFIED  
BY KALAMAZOO COUNTY  
REMONUMENTATION  
PEER GROUP**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

South Witness Monument for Northwest Corner Section 5

4" X 30" Harrison Monument

Spike	N	side	10" Ash	N67°E	17.50'
Spike	E	side	15" Walnut	S26°E	15.24'
Spike	SE	side	15" Ash	S35°W	28.88'
Spike	N	side	18" Ash	N70°W	16.61'
Spike	NE	side	14" Basswood	N30°W	29.39'



Signed by

*Thomas W. Chettleburgh*

Date

November 8, 1993

Surveyor's Michigan License No.

16036