

REMONUMENTATION

NOV 21 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED  
LAKE COUNTY, MI,  
LIBER 004 PAGE 0027  
SEP 12 10 30 AM '97

For corners in

Lake \_\_\_\_\_ Located In: \_\_\_\_\_ Corner Code ## \_\_\_\_\_  
(County)

1. Public Land Survey	T 17N R 12W	M-3 ✓
	T 17N R 11W	A-3
	T _____ R _____	
	T _____ R _____	
2. Property Controlling in Section	S _____ T _____ R _____	
	S _____ T _____ R _____	
3. Miscellaneous	S _____ T _____ R _____	
Property in Sec.	S _____ T _____ R _____	

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Robert L. Wetherell February 20, 1997

I, \_\_\_\_\_, in a field survey on \_\_\_\_\_, 19\_\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-3; A-3 - Section corner common to Sec. 1, T17N, R12W and Sec. 6, T17N, R11W, Lake Co., Mi.

1837 - John Hodgson, G.L.O.

#1 - 7" Pine S68°W 5 Links

#2 - 7" Pine N31°W 16 Links

1916 - George Johnson, Co. Sur.

Found Old Stake

#3 - 8" W. Oak S58°E 40.7'

#4 - 7" W. Oak S66°W 62.8'

Undated - Co. Surveyor Records

#5 - 9" B. Oak N19°E 101.5'

1970 - George Blass, LS 5489

"T" Iron

#6 - 8" W. Pine S72°W 49.85'

#7 - 30" B. Oak N50°W 122.15'

#8 - N.W. Leg of Tower S48°E 49.65'

1973 - Clinton E. Cole, LS 17615

Same as Blass from 1970

1976 - Robert Griffin, LS 13584

Found Monument by Blass

Set 5" x 36" Concrete Monument

#6 - 8" W. Pine S72°W 49.85'

#7 - 30" B. Oak N50°W 122.15'

#8 - N.W. Leg Tower S48°E 49.65'

#9 - 4" x 7" Post West 33.13'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-3; A-3 - Section corner common to Sec. 1, T17N, R12W and Sec. 6, T17N, R11W, Lake Co., Mi.

I found U.S.F.S. Concrete Monument 10 feet East of the centerline of North and South dirt road and in centerline of old road bed to East.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Gone, #4 Found in good condition, #5 Gone, #6 Found in good condition, #7 Found Stump; #8 Found in good condition, #9 Found in poor condition.

RATIFIED BY THE LAKE CO. PEER REVIEW GROUP  
IN ACCORDANCE WITH P.A. 345

CHAIRMAN R. L. W.  
DATE 8-27-97

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-3; A-3 - Section corner common to Sec. 1, T17N, R12W and Sec. 6, T17N, R11W, Lake Co., Mi.

I accepted the U.S.F.S. Concrete Monument as a substantial marker for the corner, and is accepted as a careful and faithful re-establishment of the position of the original corner.

8" W. Oak N40°W 132.29' (60d spike in S.W. side)

18" W. Oak N69°E 113.90' (60d spike in N. side)

N.W. Leg of Tower S40°E 49.63' (O.B.T. #8)

14" W. Oak S52°W 80.77' (60d spike in S.E. side)

12" W. Pine S78°W 49.87' (60d spike in S. side) #6

18" W. Oak S68°W 64' #4

Witnessed by Robert L. Wetherell

Date 8-27-97

Surveyor's Michigan License No. 24624

