

Page 130



RECEIVED 08/20/2020 2:18:22 PM LAKE COUNTY, MICHIGAN PATTI PACOLA, CLERK/REGISTER OF DEEDS



RECORDED 08/20/2020 2-18:28 PM LAKE COUNTY, MI PATTI PACOLA, CLERK/REGISTER OF DEEDS

RECEIPT# 14597. STATION 1 S30.00 LAND CORNER

Land Corner Recordation Certificate

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name:	Craig W. McVean					Field Survey Date: May 28, 2019											
For corner(s) in:	Lake				County	-								."			
Original Public Land Survey Corner					Corner Code												
S	T		R														
\$	тт		R				В	C	D I	E F	G	Н	1	J	Κ	L	Μ,
S	T		R			- 1	-				<u></u>						71
s	T		R			⁻ 2	6		5	÷ · · 4·		3		2	· † -	-1	2
Property Controlling Corner					Corner Code	3	7 -	. .	8	 g		10		44		12 ·	3
S	Т		R			- 5										· <u>-</u>	5
S	T		R			- 1		•		` .			·		:		
S	T		R		·	- 6	18		17 -	÷ - 16		15		14	· -	13	6
S	T		R			7							-		-;		⊣7
Property Corner					Corner Code	8	19	• !	20	- 21		22		23		24	8
S 32	T	18N	R	12W	4	_ 10	30		29	- 28	} -	27		26		25	10
S 32	T	18N	R	12W	5	_ 11											11
S	Т		R			- 1	31	•	32	- 33	1 :	24		35		36 -	12
S	T		R			-12	31		32 -	+ · 30	,			33	T	30 .	-
Protracted Public Land Survey Corner					Corner Code	⁻ 13 L A	В	С	D	E F	G	Н	I	J	K	L	⊿ 13 М
s	T		_R														
S	ТТ		_ R														
S	T		_ R			_											
S	Т		R			_											

Part A: Corner History

- 4 NW 1/16 Corner Sec. 32, T18N. R12W
 - 1921 Sec. 32 Survey -
 - G. West and G. H. Johnson (PS # 405)
 - 1) B. Oak 15" S741/4°E 1251/2

- 5 CN 1/16 Corner Sec. 32, T18N. R12W
 - 1921 Sec. 32 Survey -
 - G. West and G. J. Johnson (PS # 504)
 - 1) W. Oak N571/2°W 24 1/4
 - 1938 D. S. Hazelton -
 - 2) 12" Oak N45°W 16.0; 3) W. Oak 12" S30° 16.01 1311'N to 'D11'. S. 1320' to 'D12'
 - 1952 G. Biass (PS # 5489). Survey shows corner
 - and ROW corner 33' West (#4) 1318.04' N & S. 1967 G. Blass (PS # 5489) Survey shows ROW iron 33' East (#5)
 - 2016 Unrec. Survey Wetherell Land Surveyors -File No. 13838-16. Fd. 'T' iron #5489 – 33' East of calc. corner 1318.04' – S, 1318.05' N.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

- 4 NW 1/16 Comer Sec. 32, T18N, R12W Found 7/8" x 1.4' long iron rod but no evidence of witness #1 to verify that this was the G. H. Johnson position. The intersection of 1/16 lines using the accepted 1/16 corners 1/2 mile N, S, E & W is S24°59'W 5.73' from this iron. Surveys by C. Cole, PS and P. N. Johnson, PS in this area have used the N 1/16 line as straight between the N 1/16 to the west and the CN 1/16 by Blass to the east. Thus rejected the 7/8" rod as the corner and set a 2" Alum. Cap on 5/8" x 34" rebar at the intersection of 1/16 lines per standard BLM procedure.
- 5 CN 1/16 Corner Sec. 32, T18N, R12W Fd. Rusty 1" O.D. iron pipe down 1.5' to centerline N-S gravel road per Blass - 1952. Also found a 1/2" iron - down 0.9' that is N124843'W 9.74' from the 1" pipe. This 1/2" iron is apparently the position noted by Hazelton in 1938. 1/2" iron fits Hazelton distance south to 'D12' but is 1308.38' to 'D11'. No evidence of witnesses #1, 2, or 3. No evidence that this 1/2" iron has been used as the CN1/16 corner since Hazelton. The 1" O.D. iron pipe per Blass has been used extensively for boundary surveys in this section. This 1" pipe was set midway between 'D11' and a rejected position being S6°10'E 7.82' from the accepted 'D12' position. Measured grid bearing and distance from 1" pipe of S1°23'21"W 1310.27' to 'D12' and N1°20'26"E 1318.10' to 'D11'. Thus accepted 1" O.D. iron pipe as the occupied CN 1/16 corner per Blass since 1952 and the best available evidence of the position of the corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

- 4 NW 1/16 Corner Sec. 32, T18N, R12W Stamped 2" Aluminum Cap on 5/8" x 34" long iron Rebar Set Blue Composite Post with loc. tag 1' SE S50°E 21.36' to set N & T in SW side 19" W. Pine S64°W 17.00' to set N & T in SE side 11" W. Pine N46°W 31.97' to set N & T in NE side 13" R. Pine N24°59'E 5.73' to 7/8" iron rod
- 5 CN 1/16 Corner Sec. 32, T18N, R12W Raised 1" O.D. iron pipe with stamped 2" Aluminum cap on 5/8" x 1' long iron rebar. West 32.96' to Fd. ½" I.D. iron pipe and added Blue Composite Post with loc. tag. East 32.95' to Fd. Blass 'T' iron and cap S43°W 56.80' to set N & T in NW side 9" W. Oak N59°W 68.96' to set N & T in NE side 6" W. Oak

8/19/2020

Craig W. McVean

Professional Surveyor's License No.: 39088

Prepared By: Craig W. McVean Michigan Dept. of Natural Resources 8015 Mackinaw Trail Cadillac, Michigan 49601