

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

| Lake (County) | Located In | | Corner Code # |
|---|------------|-------------|---------------|
| 1. Public Land Survey | T | R | |
| | T | R | |
| 2. Property Controlling in Section | S 7 | T 18N R 12W | 3 |
| | S 7 | T 18N R 12W | 15 |
| 3. Miscellaneous Property in Section | S | T | R |
| | S | T | R |

4. Lot No: Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on April 25, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 1 | | | | | | | | | | | | | |
| 2 | | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | | |
| 4 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | | |
| 6 | | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | | |
| 8 | | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | | |
| 10 | | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | | |
| 12 | | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

3 - 1972 - LCRC L. 2, P. 114 - C.F. Roser, PS #12028
- Set 1" X 36" pipe in approx. ctr. of N-S dirt road per standard BLM instructions. - 1) 15" Oak S78°E 54.4'; 2) 6" Oak N50°E 68.3'; 3) Set ced. Post Due West 33'

15 - 1968 - R. A. Griffin notes - iron
- 1972 - LCRC L. 2, P. 115 - C. F. Roser, PS #12028.
Recovered Bob Griffin corner of record. Found ½" X ½" Iron Rod. - 1) B. Oak 8" S28°W 23.1', 2) J. Pine 6" S35°E 52.3', 3) Spike in top J. pine stump 6" S02°W 32.9', 4) Ctr. E-W sand road Due South 2'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

3 - North 1/16 Corner common to Sec. 7, T18N, R12W and Sec. 12, T18N, R13W - Found 1" pipe 2'± West of centerline N-S road. Found witness #1 supporting position.
1" Iron pipe accepted as the best available evidence of the position of the corner.

15 - West 1/16 corner common to Section 7 and 18 - Found ½" X ½" x 1' long square Iron 1'± South of centerline E-W gravel road. Found witnesses #1 - stump, and #2 in good condition, supporting position. ½" square iron accepted as the best available evidence of the position of the corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3 - Found 1" iron pipe
N28°E 66.17' to set Nail & Tag in E. side 5" Oak
S80°E 55.14' to set Nail & Tag in S. side 20" Oak (#1)
S23°W 61.77' to set Nail & Tag in E. side 10" Oak
N52°W 48.96' to set Nail & Tag in SW side 5" J. Pine
Set Blue Carsonite Post with location tag 33' West @ old post hole

15 - Replaced ½" x 1 ½" x 1' long iron with stamped 2" Aluminum cap on 5/8" x 34" rebar
N07°E 53.44' to set Nail & Tag in W. side 20" Oak
N48°E 89.96' to set Nail & Tag in NW side 15" W. Pine
S35°E 52.58' to set Nail & Tag in SW side 11" J. Pine(#2)
N60°W 79.62' to set Nail & Tag in NE side 7" W. Pine
Set Blue Carsonite Post with location tag 33' South

Signed by:

Craig W. McVean

Date:

10/25/2011

Surveyor's Michigan License No.:

39088

