

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 19 N. R. 11 W.	B-11; B-13; C-13
2. PROPERTY CONTROLLING IN SECTION	T. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION 32	T. 19 N. R. 11 W.	XX(822.73 W of D-12 & 1,810.01 E of C-12)
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April 22, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on May 20, 1976, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of corner monument and accessories established to perpetuate locating the position of the corner:~~
C. (continued)

XX
Set 1/2"x3/8"x18" iron &
cedar post w/loc. tag
5" W. Pine S20°E 20.25
9" B. Oak N75°W 9.80
Old E-W fence Due N 6

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- B-11 Reestablished quarter corner on line between section corners to E & W and at prorated distance to G.L.O. survey.
 - B-13 Found 1 1/4" pinch pipe; George Johnson notes call for 1 1/4"x3' pipe.
 - C-13 Reestablished corner common to Sec. 31 & 32, on S line of T19N-R11W, equidistant and on line between found S 1/4 corners of Sec. 31 & 32.
 - XX Established NE corner of W 3/8 of NE 1/4 of SW 1/4 of Sec. 32; on N line of SW 1/4 Section 32 and 822.73'; N89°45'40"W of center of Section 32.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-11	B-13	C-13
Set 5"x5"x48" conc. mon. w/ bronze cap & cedar post	Found 1 1/4" pipe added DNR mon. & cedar post	Set DNR Mon. & cedar post
7" W. Pine S55°E 69.1	5" J. Pine N25°W 9.2	13" R. Oak N75°W 33.2
10" W. Pine S60°W 60.0	3" J. Pine S35°W 3.6	6" R. Oak N55°E 11.6
4' stream C-N'y	N 1/4 Sec. 6, T18N-R11W	NE Corner Sec. 6, T18N-R11W
Due W 132	S89°58'30"E 72.85	S89°58'30"E 79.20
E-W trail Due N 10'±		

SIGNED BY Carl F. Roser 4-28-77 DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE

MICHIGAN REGISTERED LAND SURVEYOR



(SEAL)

ELLSWORTH TOWNSHIP
LAKE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____