

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Lake _____
(County)

Located In

Corner Code #

1. Public Land Survey	T	19N	R	12W	G13
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

Register of Deeds Stamp & File Number

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on Sept. 19, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

G13 – 1837 – J. Hodgson – A tamarack 12" dia. for corner
- 1973 – LCRC – L. C002, p. 152 – C. F. Roser (PS #12028)
Reestablished corner per Standard BLM instructions
Set DNR Mon. and Cedar Gd. Post
1) 14" Hemlock N35°W 68.8'
2) 17" Maple N28°E 14.0'
3) 9" Cedar N66°E 18.9'
4) Cor. To Sec. 3 & 4 due E. 8.53'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G13 – Standard Corner common to Sections 33 & 34, T19N, R12W – Fd. 4" Dept. of Conservation (DOC) Aluminum Cap on 1" iron pipe in swamp. No GLO evidence was found. Witnesses #1 to 3 are gone. DOC Monument accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G13 – 4" DOC Aluminum Cap on 1" iron pipe.
S85°W 22.66' to set Nail & Tag (N & T) in S. side 8" Y. Birch scribed 'SCBT'
N37°W 33.03' to set N & T in NE side 9" R. Maple
N08°W 31.9' to set N & T in W. side 12" Hemlock
East 8.53' (8.58' – GLO) to 'G1', T18N, R12W – DOC Monument (#4)



Signed by:

Craig W. McVean

Date:

8/12/2014

Surveyor's Michigan License No.:

39088