

SURVEY &
REMONUMENTATION

OCT 29 1996

COMMISSION

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 96 OCT -2 AM 11:05

For corners in

LAPEER

(County)

Located In:

Corner Code #

10N 11E

J-13

1. Public Land Survey

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

EARL E. GRAVLIN

AUGUST

96

I, in a field survey on , 19 ,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration.

History: Parke, 1833, Set quarter Section Post, Bearings B.Ash, 12 N.64 E.33, Beech 9
N.39W.12 1/2, The Bearing trees are marked. County Surveyor, Bates, 1867 Stake & 2
stones, 16.10.5, 16.9.9. Beech 8 S.63W. 40, . Act 74 none. Recorded Surveys, Kay,
Liber 002, Page 464, N70°E 40.41' 30" Elm, N35°W 61.73' 8" Hickory, S10°W 16.85' 40"
Elm, Gravlín Land Survey, Liber 11, Page 304, Found 1/2" Iron, N40°E 34.56' End CMP,
N75°W 41.27' N/S 8" Oak, S05°W 10.14' E. Leg Sign.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

GRAVEL ROAD TO WEST, EAST AND NORTH, I-13 TO J-13 2656.70

PEER GROUP
APPROVED LAND CORNER
PA 345 OF 1990
LAPEER COUNTY

RAY DAVIS P.S. CO. SURVEYOR
DATE 9-10-96

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-13 SOUTH 1/4 CORNER, SECTION 35, T10N-R11E
FOUND 1/2" IRON, SET BRASS CAP
N40°E 34.56' NORTH END CMP
N75°W 41.27' NAIL AND TAG N/S 8" OAK
S05°W 10.14' EAST LEG SIGN
S80°W 7.32' NORTH LEG SIGN



Signed by Date 10-1-96

Surveyor's Michigan License No. 23510