SURVEY & REMONUMENTATION

FEB 2 6 1998

C (\sim τ	At

Surveyor's Michigan License No. 28420

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	•	
Leelanau Located In: Corner Code #	12/31/97	
1. Public Land Survey T 30NR 11W A-11 T R	Barbara Kirt 12/31/97 Leelanau Res of Deeds 10:21 am EJK Fee: 9.00 04E00002 PO232 Pase 1 of 1	
2. Property Controlling in Section S TR	#535 Register of Deeds Stamp & File Number	
4. Lot No, Recorded Plat	ructions of the of Law and for 6 18 17 16 15 14 13	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36	
A Description of original monument and accessories and/or subsequent restoration A-11: Section Corner Common To Sections 30 and 31. G.L.O. Notes: Set Post Corner 30, 31, 25 & 26 Beech 8", N67°W, 32 Links Beech 4", S64°W, 8 Links Sugar 9", S68°E, 25 Links Sugar 20", N32°E, 14 Links	APPROVED LAND CORNER P.A. 345 OF 1990 LEELANAU COUNTY DATE: 12-1-97 COUNTY REP. M. O. M.	
B. Description of corner evidence found and/or method applied in restoring or re A-11: Section Corner Common To Sections 30 and 31. Found 7/8" Rerod w/cap no. 19846 NE Corner of House on South Side of Road, 106. SE Corner of House on North Side of Road, 133. Apple, S65°E, 82.52'	521	
	·	
C. Description of monument for corner and accessories established to perpetual A-11: Section Corner Common To Sections 30 and 31. 7/8" Rerod w/cap accepted as the best available corner by the Leelanau County Peer Review Grows 3/4" I.D. by 3.0' long galvanized iron pipe w	ple evidence of the position of the original pup on December 1, 1997. Replaced with a with stamped brass cap.	
SW Corner of House, N83°E, 263.10' SE Cor	rner of House, N60°W, 133.67 Micholas M. Aple, N80°W, 120.21' NICHOLAS M. A O'NON	