

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>32</u> ^{N.} <u>10</u> ^{W.}	<u>B-5; B-6</u>
2. PROPERTY CONTROLLING IN SECTION_____	T. _____ S. _____ R. _____ E. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION <u>18</u>	T. <u>32</u> ^{N.} <u>10</u> ^{W.}	<u>ZZ = 1620.0' S of</u> <u>A-6</u>
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 30, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on October 25, 1979, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- B-5** Fd. square conc. monument for N $\frac{1}{4}$ corner Sec. 18 T32N-R10W, per survey by H. H. Brehmer, Co. Surveyor, 1951.
- B-6** Fd. round conc. mon. for center Sec. 18 T32N-R10W that fits Brehmer survey 1951.
- ZZ** Fd. 3"x60" long pointed post bottom 1'± under water, in muck, for U.S.M.C. at S'y terminus of W line of Sec. 18 at meandered lake. Fits U.S.B.T. remains 18" tamarack stump showing decayed & partial healed-over upper face w/scribe marks, N38°W 17.2'; note U.S. called for 9" tamarack & T.A. & W.O. Green fd. the corner on May 14, 1906, & may have re-marked the tamarack. A cedar stump N39°W 19.5' is also evident, probably Green's or Brehmer's witness.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-5	B-6	ZZ
Fd. sq. conc. mon. & added	Fd. rnd. conc. monument	Fd. post bottom; replaced w/1½"
cedar post w/loc. tag	5" Ironwood N87°E 21.50	x12' pipe w/1"x24" pipe w/alum. Dept
25" Spruce S75°E 45.23	6" Maple N40°E 39.79	cap on top, 2'± above water level
6" Ash S05°E 20.03	Cor. fn. post S75°E 16.0	USBT 18" Tam. Stp. N38°W 17.2
8" Oak S28°W 6.36	Set ced.post w/loc. tag	14" Cedar N35°W 19.5
	West 38'	3" Cedar N10°W 38.0
	Ctr. N-S grvl.rd. W 5'±	7" Cedar N63°E 33.6

SIGNED BY Carl F. Roser 5-14-80 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

LEELANAU TOWNSHIP
LEELANAU COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET