

JAN 25 2000

Filed under Remonumentation Act 345 of 1990
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

LIBER 1 PAGE 348
STATE OF MICHIGAN
LENAWEE COUNTY
FILED

For corners in

Lenawee
(County)

Located In:

Corner Code #

1. Public Land Survey	T - 5 - S	R - 2 - E	G-11
	T	R	
	T	R	
	T	R	
2. Property Controlling In Section	S	T	R
	S	T	R
3. Miscellaneous Property in Sec	S	T	R
	S	T	R

29 SEP 1999 5:58:17 PM

VICTORIA J. DANIELS
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard, in a field survey on July 20, 19 99, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1824, Hervey Parke set post corner Sec.'s 27, 28, 33 & 34 W. Oak 30 N 72 E 21
Early 1900's J.L. Richard's records call for stone (Record of Dowling)
1928 J.L. Richard drove R.R. spike at intersection of highways at the P.O.E. of the Wolf Creek Highway survey
1938 Corner part of boundary of Assessor's Plat No. 1 Village of Onsted
1974 Werner Sommer found pinched top iron pipe and recorded it in Liber 2, Page 619
1995 Steve Young found P.K. nail

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 20, 1999 Found P.K. nail at surface over 8" piece of pinched iron 8" deep and R.R. spike 0.10 south of the pinched iron. Replaced the pinched iron with 5/8" X 3' re-rod and set monument box.
Hit bricks 2 1/2' deep and drove the re-rod through them.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Assessor's Plat monument N 45° W 46.98
Cut "X" on face of West post of sign N 35° E 71.85
Survey mark spike & Lenawee County re-mon tag in NE face E.P. S 60° E 49.05
NE Cor. of brick school house S 45° W 123.59



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date September 14, 1999

Signed by Glenn E. Richard Date Sept. 23, 1999
Glenn E. Richard

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN, 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993