

JAN 25 2000

SECTION

Filed under Remonumentation Act 345 of 1990
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 1 PAGE 323
STATE OF MICHIGAN
LENAWEE COUNTY
FILED

For corners in

Lenawee
(County)

Located in:

Corner Code #

14 JUL 1999 6:32:51 PM

VICTORIA J. DANIELS
REGISTER OF DEEDS

1. Public Land Survey T - 5-S R - 5-E G-12
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard, in a field survey on July 6, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1819 Joseph Fletcher set 1/4 Sec. post Hickory 12 S 4 W 15 Hickory 12 N 47 E 28
Couldn't find any information on this corner in all of the old survey records.
1981 I re-established the corner by setting a 3/4" iron pipe in the pavement in line with old fence lines E & W and by doubling the distance from the computed N. & S. 1/4 line and the occupied east 1/8 line of Section 33 and recorded it in L 5 P 10
1997 Found 3/4" iron pipe. Replaced it with 3/4" X 3' iron pipe and set monument box in newly layed asphalt pavement

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 6, 1999 Found 3/4" iron pipe in monument box. Drove the iron pipe down with 5/8" X 3' re-rod inside of it and capped with Lenawee County Re-mon cap stamped P.S. 13040

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Cut "X" on CMP S 30° E 53.61
Cut "X" on CMP S 40° W 36.00
Cut "X" on CMP S 70° W 25.30
Fd capped re-rod "SAY #25885" East 33.00



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date June 22, 1999

Signed by Glenn E. Richard Date July 8, 1999
Glenn E. Richard

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1971

REVISED MAY 14, 1975

REVISED JAN, 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993