

JAN 25 2000

SECTION

Filed under Remonumentation Act 345 of 1990
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 1

PAGE 378
STATE OF MICHIGAN
LENAWEE COUNTY
FILED

For corners in

Lenawee
(County)

Located In:

Corner Code #

1. Public Land Survey

T-6-S R-3-E

C-11

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec

S T R

S T R

7 DEC 1999 1:04:20 PM

VICTORIA J. DANIELS
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard, in a field survey on November 1, 19 99, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1824 John Mack Set post cor. Sec.'s 29, 30, 31 & 32 Beech 16 N 73 W 11 Basswood 18 S 65 E 53
I could not find any information on this corner
1958 I found a iron pipe under a large stone at north edge of gravel road
1964 I found a iron bar at north edge of road
1972 Kenneth Suydam "Found 3/4" iron" and recorded it in Liber 1, Page 473
1991 & 1992 I found iron pipe

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Nov. 1, 1999 Found 3/4" X 19" iron pipe over 5/8" iron bar on the east side of stone 30" deep. Set 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in a monument box at location of the found iron pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Cut "X" in CMP N 30° E 44.29
Found 60 penny spike in 18" Osage tree S 10° W 29.60
Found concrete nail & disc in E. pole S 40° W 48.96
Found nail & disc in face of TP N 45° W 41.85

The corner is 2' East of centerline of pavement and 6' North of centerline of pavement

Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date November 23, 1999

Signed by Glenn E. Richard Date Dec. 1, 1999
Glenn E. Richard

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197
REVISED MAY 14, 197
REVISED JAN, 197
ADAPTED FOR WORD PROCESSING MARCH, 197

