

DEC 22 1998

SECTION

Filed under Remonumentation Act 345 of 1990
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 1 PAGE 300

STATE OF MICHIGAN
LENAWEE COUNTY
FILED

For corners in

Lenawee
(County)

Located In:

Corner Code #

- | | | | |
|------------------------------------|---------|-----------|-----|
| 1. Public Land Survey | T - 6-S | R - 3 - E | D-9 |
| | T | R | |
| | T | R | |
| | T | R | |
| 2. Property Controlling in Section | S | T | R |
| | S | T | R |
| 3. Miscellaneous | S | T | R |
| Property in Sec | S | T | R |

16 DEC 1998 4:16:01 PM

VICTORIA J. DANIELS
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard, in a field survey on December 12, 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1824 John Mack set 1/4 post Cor Elm 8 S 21 W 13, B. Oak 9 N 15 E 24
Early 1900's J.L. Richard's record "Found stone, set tile on top"
1920 Harold Clegg surveyed Wolf Creek Highway, found stone and set iron pipe 0.3 E., NW cor school hse S 39 E 77.1
1967+ Jack Gillin (Road Commission employee) set a monument box
1967 I found an iron pipe in monument box
1973 I found iron pipe in monument box and recorded it in L. 2, P. 479, NW cor school hse (resided) 76.70
1989 I found iron pipe in monument box under asphalt pavement cap. Raised to surface with iron pipe
1994 Steven Young found re-rod? and raised with P.K. nail
1995 Michael Bartolo found P.K. nail

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

November 13, 1998, Found P.K. nail which agrees reasonably with 1973 witnesses over iron pipe in monument box 6" deep. Probed and hit stone 26" deep and raised monument box with adjusting rings.
Dec. 12, 1998 Found 1" X 22" X 3' re-rod over 3/4" iron pipe bent to position over deeper stone. Replaced re-rod and found iron pipe with 5/8" X 3' re-rod. Hit stone with 5/8" X 3' re-rod. Bent it to position of found re-rod & 3/4" iron pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Fd. dbl. hd. nail & disc in Tel. pole N 80° W 139.22
Fd. 60d spike & disc in Elec. pole N 5° E 29.59
Fd. boat spike & washer in Elec. pole N 5° E 29.40
SE. corner house foundation N 30° W 174.61
NE. corner of garage (brick face) S 60° E 132.96
SW. corner house (siding) S 30° E 94.21



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date December 1, 1998

Signed by Glenn E. Richard Date Dec. 14, 1998
Glenn E. Richard

Surveyor's Michigan License No. 13040