

JAN 25 2000

Filed under Remonumentation Act 345 of 1990  
**LAND CORNER RECORDATION CERTIFICATE**  
 Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

LIBER 1 PAGE 374

For corners in

Lenawee  
 (County)

Located In:

Corner Code #

STATE OF MICHIGAN  
 LENAWEE COUNTY  
 FILED

7 DEC 1999 1:03:20 PM

VICTORIA J. DANIELS  
 REGISTER OF DEEDS

Register of Deeds Stamp &amp; File Number

1. Public Land Survey T-6-S R-3-E G-10  
 T R  
 T R  
 T R  
 T R  
 2. Property Controlling S T R  
 in Section S T R  
 3. Miscellaneous S T R  
 Property in Sec S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

I, Glenn E. Richard, in a field survey on November 11, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1824 John Mack Set 1/4 Sec. post Beech 4 N 47 E 4 Elm 6 S 62 E 23  
 1884 James Blair found large stone  
 1949 Walter Frazier found large stone west of track in line of E.W. fence  
 1964 I found stone 20'± west of road center line and 10'± east of creek  
 1965 I used this stone for the point of beginning for the Plat of Birnwick recorded in Liber 15, Pages 46 & 47  
 1972 I found stone, raised with 3/4" iron pipe and recorded it in Liber 2, Page 23

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Nov. 11, 1999 Found 3/4" iron pipe over stone 27" deep. Drilled hole through stone & set 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040. Set monument box and placed asphalt around box which is 9'± west of the west edge of the pavement.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

dbl. hd. nail & re-mon tag in 8" Walnut S 20° W 11.82  
 dbl. hd. nail & re-mon tag in 14" Ash N 80° W 50.01  
 Fd. dbl. hd. nail & disc in 16" Basswood N 35° W 29.15  
 Fd. dbl. hd. nail & disc in 8" Elm N 60° E 66.25  
 Fd. dbl. hd. nail & disc in T.P. N 75° E 55.85

Centerline of pavement East 19.9



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date November 23, 1999

Signed by Glenn E. Richard Date Dec. 1, 1999  
 Glenn E. Richard

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1971

REVISED MAY 14, 1975

REVISED JAN., 1993

ADAPTED FOR WORD PROCESSING MARCH, 1993