

JAN 2 2 2001

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

RECTION

For corners in

Filing Requirement of Act 74, Mich. P.A. 1970

Lenawee (County)	_ Located In:	Corner Code #						ENAME	MICHIO E COUNT LED	
1. Public Land Survey	Public Land Survey T <u>-6 - S R - 4 - E D - 7 </u>						28 JUN 2000 8:42:54 AI VICTORIA J. DANIELS REGISTER OF DEEDS			
3. Miscellaneous S					Deeds					 1
4. Lot No, Recorded Plat		2 3	6	5	4	3	2	1		
			4 5	7	8	9	10	11	12	
t, <u>Glenn E. Richard</u> , in a field survey on <u>February 09, 2000</u> , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned		6 7	18	17	16	15	14	13		
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5			8	19	20	21	22	23	24	
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:			30	29	28	- 27	26	25		
,	orners, all in the same town an	d range, may be recorded	12 13	31	32	33	34	35	36	
A. Description of original monument and accessories and/or subsequent restoration: G.L.O. 1819 Joseph Fletcher set 1/4 Sec. post W. Oak 14 N 26 E 44 W. Oak 12 N 40 E 33 1838± Section 17 was subdivided J.L. Richards record= gas pipe Oak S. about 45 E 96 1/2 = 63.69' 1941 P.O.B. Plat of Suburban Acres 1952 & 1953 Kenneth Suydam shows corner on notes but not type of monumentation 1954 P.O.B. Plat of Pine Grove 1960 & 1962 Kenneth Suydam shows corner on notes but not type of monumentation 1967 I set PK nail from monuments on Plat of Pine Grove 1972 Werner Sommer found P.K. nail & washer and recorded it in L 2 P 97 S.E. cor of house N 20 W 88.66 feet Nail & disc in 26" Oak S 50 E 63.68 1993 Kenneth Suydam set a cotton gin spike for N 1/4 corner of Section 20 June 1, 1999 I found cotton gin spike 3" below the surface of new asphalt pavement. Dug and found 1 1/4" iron pipe and bricks 20" deep 0.61 West of the location of the cotton gin spike. Couldn't remove the iron pipe, set 5/8" X 3' re-rod in the top & drove them both down and set monument box.										
·	Found re-rod in monument b	l applied in restoring or reestablis	•			e Cou	anty R	e-mor	n cap	

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner

S.E. corner of house foundation N 15° W 88.47 feet S.W. corner of house foundation N 40° E 101.91 feet Fd. nail & disc in 36" Oak S 65° E 64.59 Plat monument North 33.05 feet N. face of the base of 3" steel post in concrete South 31.64 feet

Survey mark spike & re-mon tag in E.P. N 65° W 81.88

Date June 5, 2000 Glenn E. Richard

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

OF MICHIGA

GLENN E.

RICHARD

No. 13040

E JANOSONAL S

PAGE 393

LIBER 1