

JAN 22 2001

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Lenawee
(County)

Located in:

Corner Code #



LIBER 1

PAGE 396

STATE OF MICHIGAN
LENAWEE COUNTY
FILED

28 JUN 2000 8:42:54 AM

VICTORIA J. DANIELS
REGISTER OF DEEDS

1. Public Land Survey T-6-S R-4-E G-7
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec S T R

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard, in a field survey on February 09, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1819 Joseph Fletcher set post cor sec's 15, 16, 21 & 22 W. Oak 8 N 40 W 5 W. Oak 6 N 37 E 5
1837 Section 16 was subdivided
1907 J.L. Richard's records called for stone in sight N.W. corner of Town House S 1/2 W 76 1/4 (50.33") S 23 E 85 1/4 (56.27")
1959 Kenneth Suydam "Set Sec. corner by Witt"
1964 I set 1/2" X 4' iron pipe using the witnesses from the Town Hall
1965 I found iron pipe
1973 Werner Sommer Found iron pipe and recorded it in Liber 2, Page 311
1975 I found iron pipe
1979 I found iron pipe 5' South of South edge of road
1984 Kenneth Suydam found iron pipe S. of road
1997 Steven Young found 3/4" iron pipe which checked the witness.
1999 Found 3/4" iron pipe 2.3 south of south edge of pavement. Replaced it with a 5/8" X 3' re-rod.
Also set monument box and placed asphalt paving around it.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

February 9, 2000 Found 5/8" re-rod in monument box, checked witnesses and capped with Lenawee County Re-mon cap stamped P.S. 13040

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner

Corner is 2.3 south of south edge of pavement
Fd dbl hd nail & disc in 14" Locust N 48.45
Fd. "X" cut on E. end of concrete culvert S 75° E 54.47
Carsonite survey marker post South 19.90
dbl. hd. nail & disc in 8" Maple S 80° W 159.72



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date May 9, 2000
Signed by Glenn E. Richard Date June 6, 2000
Glenn E. Richard
Surveyor's Michigan License No. 13040