

SURVEY & REMONUMENTATION

Filed under Remonumentation Act 345 of 1990

APR 28 1995

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 56

COMMISSION

For corners in

Lenawee (County)

Located In:

Corner Code #

1. Public Land Survey T-6-S R-5-E H-11
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. Recorded Plat
5. Private Claims

I, Glenn E. Richard, in a field survey on October 24, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. August 1819, Joseph Fletcher Dogwood 6 N 60 E 26, W. Ash 5 N 36 W 30
September 1881, James Blair "Found old stake", set new stake and stone.
September 1915, J.L. Richard, S 1/4 corner (no description) 0.5 North of road center line.
August 13, 1974, I dug and found pointed stone and added 3/4" X 4' iron pipe and recorded it in L. 3, P. 299, NE. Cor. house foundation S 25° W 146.55

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

October 24, 1994, Dug through pavement and found iron pipe. Replaced the iron pipe with 3/4" X 3' iron pipe (ove a 3/4" X 16" iron pipe) capped G.E.R., P.S. 13040 in a monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe capped G.E.R., P.S. 13040 and is accepted as a careful and faithful perpetuation of the position of the original corner.
NE. Cor. of conc. block house found. S 25° W 146.51
NW Cor. of conc. block found of porch S 35° W 167.80
Dbl. hd. nail & disc in south face of Elec. Pole S 80° W 167.98
Cut "X" on C.M.P. North 19.22
Cut "X" on C.M.P. N 45° W 30.91



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date November 3, 1994

Signed by Glenn E. Richard Date Nov. 14, 1994

Surveyor's Michigan License No. 13040