

SURVEY &  
REMONUMENTATION

JAN 15 1998

Filed under Remonumentation Act 345 of 1990

LIBER 1 PAGE 212

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
LENAWEE COUNTY  
FILED

17 OCT 97 3:55 P.M.

VICTORIA J. DANIELS  
REGISTER OF DEEDS

For corners in

Lenawee  
(County)

Located In:

Corner Code #

1. Public Land Survey

T - 7 - S R - 5 - E

A - 7

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec

S T R

S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Glenn E. Richard, in a field survey on September 06, 19 97,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1819 Joseph Fletcher Intersect W. Bdg. 43 lks N. of post Set post at intersection cor. sec. 18 & 19  
Beech 10 S 45 E 34 Beech 40 N 40 W 29  
1882 James Blair "Found a stake" 40 lks (26.40') North of stake at Palmyra corner  
1975 I set a R.R. spike 26.40' N. of M-7 T7S R4E using Blairs record angle in the SE corner of Section 13,  
T7S R4E and recorded it in Liber 3 P 339.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Sept. 4, 1997 Found R.R. spike in pavement 0.06 West of line between M-6 and M-7 T7S R4E  
Sept. 6, 1997 Found bricks when setting monument box. Set 3/4" x 3' gas pipe capped G.E.R. 13040 in  
box 26.40 feet north of M-7 T7S R4E on line to M-6, Len. Co. Rd. Comm. had just layed new asphalt  
pavement.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe capped G.E. R. 13040 in monument box and is accepted as the best available evidence  
of the position of the original corner.

SW corner of house foundation N 55° E 124.39  
NE corner of house foundation S 40° W 159.50  
Survey mark spike & re-mon tag in E.P. N 75° W 32.60  
Found dbl hd nail & disc in E.P. S 50° E 42.06  
Found dbl hd nail & disc in E.P. S 45° W 65.30  
3/4" iron pipe in monument box at M-7 T7S R4E South 26.40



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date Sept. 30, 1997

Signed by Glenn E. Richard Date Oct. 7, 1997  
Glenn E. Richard

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993